Form 3160-5 (November 1983) (Formerly 9-331) DEPARTM	IN D STATES.	SUBMIT IN TRIPI	
BUREAU OF LAND MANAGEMENT NEW HEXCO SU240			LC 031740-B
SUNDRY NOT	CES AND REPORTS C lis to drill or to deepen or plug ba FION FOR PERMIT-" for such pr	ON WELLS ack to a different reservoir. oposais.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL X GAS OTHER			7. UMER AGEREMENT NAME Eunice Monument South Uni
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Chevron U.S.A. Inc.			9. WELL NO.
P. O. Box 670, Hobbs, NM 88240			210
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND FOOL, OE WILDCAT Eunice Monument
· ·			11. SBC., T., R., M., OR BLE. AND SURVEY OR ARMA
3261' FNL & 1980' FWL			Sec 4 T21S R36E
14. PERMIT NO.	16. ELEVATIONS (Show whether DF. 3567' DF	RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE Lea NM
16. Check App		ature of Notice, Report, or C	Other Data
TEST WATER SHUT-OFF	CLL OR ALTER CASING	WATER BRUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	ALTERING WELL
(Other)		(Nors: Report results Completion or Recomp	of multiple completion on Well letion Report and Log form.)
Plug back open hole f Perforate from 3650'			······
Equip well to pump.	Return to production	1	·
·			
<u> </u>			
18. 1 hereby certify that the foregoing is SIGNED H. Bul		ision Drilling Manage	er <u>date</u> <u>4-30-1986</u>
(This space for Federal or State office APPROVED: 47.	use)		DATE 5784
CONDITIONS OF APPROVAL, IF AN		· · · · · · · · · · · · · · · · · · ·	##### <u></u>

.

*See Instructions on Reverse Side