

C - CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
Federal

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER - Injector

Name of Operator
Chevron U.S.A. Inc.

Address of Operator
P.O. Box 670 Hobbs, NM 88240

Location of Well
4630 South 3235 North 1980
UNIT LETTER 9 FEET FROM THE LINE AND FEET FROM
East LINE, SECTION 4 TOWNSHIP 21S RANGE 36E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3562' GL

7. Unit Agreement Name
Eunice Monument South Unit

8. Farm or Lease Name

9. Well No.
209

10. Field and Pool, or WHdcat
Eunice Monument G/SA

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
PERMANENTLY ABANDON ☐ CHANGE PLANS ☐
OR ALTER CASING ☐ OTHER ☒ Convert to injector

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean out well to TD @ 3871'. Add perforations from 3675' - 3695'. Acidize as necessary. Equip for injection. Test casing, packer, and tubing to 500 psi for 30 minutes. Return to production as an injector.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

P. H. Bailey Jr. TITLE Division Drilling Manager DATE 8-25-1986
Orig. Signed by
Paul Kautz
Geologist
DATE AUG 27 1986