

IL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Water Injector	7. Unit Agreement Name Eunice Monument South Unit
2. Name of Operator Chevron U.S.A. Inc.	8. Farm or Lease Name
3. Address of Operator P.O. Box 670 Hobbs, NM 88240	9. Well No. 181
4. Location of Well UNIT LETTER 660 FEET FROM THE North LINE AND 1980 FEET FROM East 4 21S 36E TOWNSHIP RANGE NMPM.	10. Field and Pool, or Wildcat Eunice Monument
11. Elevation (Show whether DF, RT, GR, etc.) 3538' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Convert to injector	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to clean out well. Acidize as necessary. Equip for injection. Test casing, tubing, and packer to 500 psi for 30 minutes. Place well on injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>P.H. Bullock Jr.</u>	TITLE <u>Division Drilling Manager</u>	DATE <u>4-28-1986</u>
PROVED BY <u>Eddie W. Seay</u>	TITLE <u>Oil & Gas Inspector</u>	DATE <u>MAY 1 - 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		