

O CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
DATE	
BY	
TO	
FROM	
NO. OFFICE	
BY	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

☒ WELL ☐ GAS ☐ OTHER		7. Unit Agreement Name Eunice Monument South Unit
8. Operator Chevron U.S.A. Inc.		8. Form or Lease Name
9. Address of Operator P.O. Box 670 Hobbs, NM 88240		9. Well No. 200
10. Location of Well LETTER <u>E</u> <u>1941/480</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM <u>West</u> <u>4</u> LINE, SECTION <u>21S</u> TOWNSHIP <u>36E</u> RANGE <u>4</u> NEPM.		10. Field and Pool, or Whichever Eunice Monument G/SA
11. Elevation (Show whether DF, RT, GR, etc.) 3563' GL		11. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
ALTER CASING ☐	OTHER ☒ Add perforations, Acidize	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

Write Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed operations) SEE RULE 1103.

Clean out to 3855'. Log well. Add additional Grayburg perforations as logs indicate. Acidize as necessary. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

M. E. Abner TITLE Staff Drilling Engineer DATE 12-23-1986
 ORIGINAL SIGNED BY JERRY SEXTON
 DISTRICT 1 SUPERVISOR
 DATE DEC 29 1986
 NO. OF APPROVAL, IF ANY: