

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK	<b>X</b>	NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER) <b>Fracture Treat</b>	<b>X</b>

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

Hobbs, New Mexico

October 25, 1957

(Place)

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Gulf Oil Corporation

Ball-Ramsay "A"

Well No. 9

in E

(Company or Operator)

Lease

(Unit)

SW 1/4

NW 1/4

1/4 of Sec. 4

T. 21-S

R. 36-E

NMPM,

Runice

Pool

(40-acre Subdivision)

Lea

County.

FULL DETAILS OF PROPOSED PLAN OF WORK  
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

It is proposed to fracture treat as follows:

- Lead hole with salt water, pull rods, pump and 2-3/8" tubing.
- Check total depth with steel line measurement, clean out if necessary. Run Caliper and Gamma Ray-Neutron log to find point to PB with Hydramite.
- Run 2-7/8" tubing w/ Lynes formation packer with setting as shown by logs.
- Swab tubing dry; break formation with lease oil and treat open hole below packer with 7,500 gallons 24 degree refined oil with 1# sand per gallon. 6500 PSI surface pressure.
- Inject lease oil w/ crushed moth balls to block treated formation.
- Repeat above treatment; flush, then overflush w/ 75 barrels lease oil.
- Pull 2-7/8" tubing and Lynes Packer, r-run 2-3/8" tubing, pump and rods.
- Swab and test, return well to production.

Approved....., 19.....  
Except as follows:

Gulf Oil Corporation

Company or Operator

By.....

Area Supt. of Production

Position.....

Send Communications regarding well to:

Approved  
OIL CONSERVATION COMMISSION

By..... Name..... Gulf Oil Corporation

Title..... Address..... Box 2167 - Hobbs, New Mexico