## STATE OF NEW MEXICO ERGY AND MINERALS DEPARTMENT C \_ CONSERVATION DIVISION DISTRIBUTION Form C-103 -P. O. BOX 2088 Revised 10-1-78 SANTA FE SANTA FE, NEW MEXICO 87501 FILE 5a. Indicate Type of Lease U.1.0.1. State LAND OFFICE 5, State Oil & Gas Lease No. OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO ORICL OR TO DEEPEN OF PLUG BACK TO A DIFFI USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name WELL \_\_\_ other- Injector Eunice Monument South Unit une of Operator 8. Fam of Lease Name Chevron U.S.A. Inc. idress of Operator 9. Well No. P.O. Box 670 Hobbs, NM 88240 cation of Well 10. Field and Pool, or Wildcat Eunice Monument G/SA 15. Elevation (Show whether DF, RT, GR, etc.) 12. County Lea 35841 62 Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TORM REMEDIAL WORK PLUG AND ABANDON COMMERCE DRILLING OPHS. ARILY ABANDON OR ALTER CASING CASING TEST AND CEMENT JOS Deepen and convert to injection Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

Clean out to TD @ <u>3899</u>. Deepen well from <u>3899</u>' to <u>4001</u>'. Log well. Add additional Grayburg perforations as logs indicate. Acidize as necessary. Equip for injection. Test casing, packer, and tubing to 500 psi for 30 minutes. Return to production as an injector.

hereby certify that the information above is true and complete to the best of my knowledge and belief.

Division Drilling Manager

ORIGINAL SIGNED BY FERRY SEXTEN

ORIGINAL SIGNED BY VERRY SEXTON
DISTRICT LAUPZEVISOR

SFP 1 1 1986