

CONSERVATION DIVISION
P. O. BOX 2038
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐	GAS WELL ☐	OTHER- ☐ Injector	7. Unit Agreement Name Eunice Monument S. Uni
Name of Operator Chevron U.S.A. Inc.			8. Form or Lease Name
Address of Operator P.O. Box 670 Hobbs, NM 88240			9. Well No. 251
Location of Well UNIT LETTER <u>V</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>6</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> NMPM.			10. Field and Pool, or Wildcat Eunice Monument G/SA
15. Elevation (Show whether DF, RT, GR, etc.) 3590			12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
PORABLY ABANDON ☐	CHANGE PLANS ☐
OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☒ <u>dpr, log, eval f/perfs, acdz</u>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 4059 PB: 4059 2-14-88 through 2-10-88

POOH w/ prod. equip. Change out wellhead to national 7 1/16". Cleanout and drlg hydromite f/3857-3886, drlg new formation f/3886 to 4050', circ. clean. Log, WL TD 4062', WL csg shoe at 2796', csg set at 3796', ran caliper f/TD to 3550', CNL f/TD to 2900, GR, CCL f/TD to surf. Pmp 50bbls CKF down casing, RIH w/ 2 3/8" IPC tbg to 3753', pmp 66 bbls pkr fluid, ND BOP, set pkr at 3759', load csg w/14bbls pkr fluid, test to 600psi for 30 min., ok. NU inj wellhead and test void to 2500psi, ok. RD MO PU. Turn over to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed by <u>M. E. Ahern</u>	TITLE: <u>Staff Drlg. Engr.</u>	DATE: <u>Feb. 24, 1988</u>
Orig. Signed by <u>Paul Kautz</u> Geologist	TITLE: _____	DATE: _____
REVISIONS OF APPROVAL, IF ANY:		

R

E