Carlsbad, New Mexico January 24, 1933

Atlantic Oil Producing Co., Drilling and Producing Dep't., Dallas. Texas.

YOUR FILE: DP-B Forms. State of New Mex.

Dear Sir:

Att: Mr. Beecherl.

Regarding your state "B" well #1 in SE/4 of Sec. 8, T. 21 S., R. 36 E. Lea County New Mexico, that y u are starting. I am listing on separate sheet the reports required by our department for well drilled on state or patented lands. I am also enclosing a copy of our Bulletin #2 which contains all the details.

Our policy is to return approved copies of the following: (number to correspond with sheet) #1; 3; 5; 7; 10 and 11, Jh0.11 you desire others please attach note to the reports and we will be glad to comply with your request.

You will probably notice in Bulletin #2 that we require; <u>FIVE DAYS NOTICE</u> on several of the notices of test. I realize that it is impossible to know that far in advance and I would suggest that your local superintendant get in touch with myself by telephone about 12 to 14 hours prior to the tests on each of the three strings of pige. Also in case you want to shoot the well. In this way it will a not be necessary to wait for permission to make test.

TELEPION / Numbers: Office 208 Res. 417M

Very

Enc: Requirement list.

Carlsbad, New Mexico January 24, 1933

Atlantic Oil Producing Co., Drilling and Producing Dep't., Dallas, Texas. YOUR FILS: DP-B Forms. State of New Mex.

Dear Sir:

Att: Sr. Beecherl.

Regarding your state "B" well #1 in SE/4 of Sec. 8, T. 21 S., R. 36 E. Lea County New Mexico, that y u are starting. I am listing on separate sheet the reports required by our department for well drilled on state or patented lands. I am also enclosing a copy of our Bulletin _2 which contains .11 the details.

Our policy is to return approved copies of the following: (number to correspond with sheet) #1; 3; 5; 7; 10 and 11. Should you desire others please attach note to the reports and we will be glad to comply with your request.

You will probably notice in Bulletin 2 that we require; <u>FIVE DAYS NOTICE</u> on several of the notices of test. I realize that it is impossible to know that far in advance and I would suggest that your local superintendant get in touch with myself by telephone about 12 to 14 hours prior to the tests on each of the three strings of pige. Also in case you want to shoot the well. In this way it will not be necessary to wait for permission to make test.

TELEFION / Numbers: Office 103 Res. 417M

Very Truly yours,

Enc: Requirement list.

J. D. Hunter, State Gil & Gas inspector.