Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR RUBEAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Designation and Serial No.
		LC-031740-A
		6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to d	rill or to deepen or reentry to a different reservoir.	o. A manant, Amoute of Trice Name
USE "APPLICATION FO	DR PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
		EUNICE MONUMENT
1. Type of Well Oil Gas Well Well Wother INJECTUR 2. Name of Operator		South Unit
		8. Well Name and No.
2. Name of Operator		1 336 wiw
Cheven USA Trc 3. Address and Telephone No.		9. API Well No.
PO P	PO Ray (15) 1001	
P.O. Box 1/50 Miolano Tx 7970 Z Attn Rm 4111 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		30-025-04557 10. Field and Pool, or Exploratory Area
		EUNICE MONUMENT
160 FS/ 1 1000 - 11		11. County or Parish, State
660 FSL + 1980 FWL		
Unit N SEC 8 Tais R36E		LEA NM
12 CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPOR	T OR OTHER DATA
TYPE OF SUPMISSION	TATORE OF NOTICE, REPOR	TI, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Character of Physics
E)	Recompletion	Change of Plans New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
12 D		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
give subsurface locations and measured and true vertice	l pertinent details, and give pertinent dates, including estimated date of starting al depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled.
	at deputs for all markers and zones pertinent to this work.)*	•
mieu DOOH W/ DROW	duction Equipment SET RBP	2 3706' Dump
micos 1001, an press		1
2 sx six an too Botch mi	ix 40 sx matrix cont + 50 sx c	1'0' a day
SE OF TOP . TONICH THE	2 70 32 MARIX CMI + 30 5x C	L C pumpes down
103/4 × 51/2 AMARIAS 30 -	ox Maticip in formation 10 in cs.	- 4 21 21
		•
I CSG WOC BHRS RUN	temp logs TOC 2 15' BOC	2201 wet
= 1	- 1 1093 100 20 13 1300	$\omega > \omega / \alpha s$.
5/0W 103/4 CS9 ShOE. TIM	W WASH SD Off RBP POOH 7	TH W/W4
9 0 3950' C/o to 3991'	TOH Run production Equip	ment.
	? / /	
	. , £º₹ED .	FOR RECORD
	pto _	
MAV. **		
4. I hereby certify that the foregoing is true and correct		
> \(\lambda \lambda \lambda \tau \cdot \)	$T \cap C \cap$	~ .
Signed C. O. DOTAN	Title [A. DR]q TITHAD	NE Bate 0414191
(This space for Federal or State office use)		
Approved by	Title	Pate
Conditions of approval, if any:		Date

