

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

6. Indicate Type of Well OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name Eunice Monument South Unit
Name of Operator Chevron U.S.A. Inc.		8. Form or Lease Name
Address of Operator P.O. Box 670 Hobbs, NM 88240		9. Well No. 296
Location of Well UNIT LETTER G 1980 North 1980 East 8 21S 36E THE LINE, SECTION TOWNSHIP RANGE WMPM.		10. Field and Pool, or Wellhead Eunice Monument G/SA
11. Elevation (Show whether DF, RT, GR, etc.) 3592' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
PERMANENTLY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
DRILL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Squeeze cement existing perforations 3653 - 3717. Drill out cement and test casing and squeeze to 500 psi for 30 minutes. Clean out to 3985'. Perforate 3719 - 3752. Acidize as necessary. Equip to pump. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed by Paul Kautz TITLE Drilling Superintendent DATE 11-18-1986
Original Signed by Paul Kautz Geologist
DATE NOV 20 1986