

NEW MEXICO STATE LAND OFFICE  
SANTA FE, NEW MEXICO

3

DEPARTMENT OF THE STATE GEOLOGIST  
NEW MEXICO SCHOOL OF MINES  
SOCORRO, NEW MEXICO

MISCELLANEOUS REPORTS ON WELLS

Reports should be made within ten days of completing the work indicated and should be submitted in duplicate.

INDICATE NATURE OF REPORT BY CHECKING

REPORT ON RESULT OF SHOOTING	SUPPLEMENTARY WELL HISTORY
REPORT ON RESULT OF TEST OF WATER SHUT-OFF <b>X</b>	
REPORT ON RESULT OF ABANDONMENT	

Mr. **E. H. Wells** **Hobbs** N. Mex., **8/17** 19**34**  
State Geologist,  
Socorro, New Mexico.

Dear Sir:

Following is a report giving the results of work done as indicated above at **State A-1350**  
**Griffiths**

Well No. **2** in **NE 1/4** of Sec. **8**, T. **21a**, R. **36a**,  
N. M. P. M., **Eunice** Oil Field **Lea** County.

The plan outlined on Form SG **103** was followed except: **600# Pressure was**  
**Pumped on Casing and**  
**Allowed to stand 30**  
**Minutes.**

The results were as follows: (Give details) **Satisfactory Shutoff**

**Witnessed by Mr. J. D. Hunter.**

DUPLICATE

Witnessed **AUG 21 1934** 19**34**

**J. D. Hunter**  
STATE GEOLOGIST OR OIL AND GAS INSPECTOR.

If results of Shooting, Test of Water Shut-off or Abandonment were witnessed by an official representative of the State, the information given above does not have to be subscribed and sworn to before a Notary Public. Other reports ordinarily do not have to be subscribed and sworn to before a Notary Public.

I hereby swear or affirm that I have knowledge of the facts given above and that the same are true and correct.

Name **loyd Hunt**

Position **Foreman**

Representing **Tide Water Oil Company**  
COMPANY OR OPERATOR.

Address **Drawer "K"**

**Hobbs, New Mexico**

Subscribed and sworn to before me this.....  
day of.....19.....

NOTARY PUBLIC.

My commission expires.....