

OIL CONSERVATION DIVISION
P. O. BOX 2038
SANTA FE, NEW MEXICO 87501Form O-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☐
5b. State Oil or Gas Lease No.	
Federal ☒	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL ☐ GAS ☐ OTHER- ☒ Injector	7. Unit Agreement Name Eunice Monument South Unit
2. Name of Operator Chevron U.S.A. Inc.	8. Farm or Lease Name
3. Address of Operator P.O. Box 670 Hobbs, NM 88240	9. Well No. 299
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North 1980 West 9 LINE, SECTION 21S TOWNSHIP 36E RANGE NMPM.	10. Field and Pool, or Wildcat Eunice Monument G/SA
11. Elevation (Show whether DF, RT, GR, etc.) 3548' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
PERMANENTLY ABANDON ☐	CHANGE PLANS ☐
OR ALTER CASING ☐	OTHER ☒ Deepen & convert to injector

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Deepen well from 3870' - 3910'. Log well. Add additional Grayburg perforations as logs indicate. Acidize as necessary. Equip for injection. Test casing, packer, and tubing to 500 psi for 30 minutes. Return to production as an injector.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

[Signature] Division Drilling Manager DATE 9-2-1986

ORIGINAL SIGNED BY JERRY SEXTON

SIGNED BY DISTRICT SUPERVISOR TITLE DATE SEP 4 1986

SIGNATURES OF APPROVAL, IF ANY: