

C CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER- ☐
--	-----------------------------------	---------------------------------

Name of Operator
Chevron U.S.A. Inc.

Address of Operator
P.O. Box 670 Hobbs, NM 88240

Location of Well

UNIT LETTER I 1650 FEET FROM THE SOUTH LINE AND 990 FEET FROM THE EAST LINE, SECTION 9 TOWNSHIP 21S RANGE 36E NMPM.

7. Unit Agreement Name
Eunice Monument South Unit

8. Farm or Lease Name

9. Well No.

319

10. Field and Pool, or Whidcat
Eunice Monument G/SA

11. Elevation (Show whether DF, RT, GR, etc.)

3590' PL

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK	☐
PERMANENTLY ABANDON	☐
OR ALTER CASING	☐

PLUG AND ABANDON	☐
CHANGE PLANS	☐

REMEDIAL WORK	☐
COMMENCE DRILLING OPNS.	☐
CASING TEST AND CEMENT JOBS	☐
OTHER	☐

ALTERING CASING	☐
PLUG AND ABANDONMENT	☐

OTHER Deepen Add Perforations Acidize ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean out to TD @ 3890'. Deepen from 3890' to 3970'. Log well. Add additional Grayburg perforations as logs indicate. Acidize as necessary. Equip to pump. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Eddie W. Sony

TITLE Division Drilling Manager

DATE 10-20-1986

Eddie W. Sony

WITNESSED BY Oil & Gas Inspector

TITLE

DATE

REMARKS OR APPROVAL, IF ANY: