

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER- ☐
Name of Operator Chevron U.S.A. Inc.		
Address of Operator P.O. Box 670 Hobbs, NM 88240		
Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>10</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.) 3580' GE		

7. Unit Agreement Name Eunice Monument South Unit
8. Farm or Lease Name
9. Well No. 317
10. Field and Pool, or Whidcat Eunice Monument G/SA
12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
FORABLY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
OR ALTER CASING ☐		CASING TEST AND CEMENT JOBS ☐	
OTHER ☒ Deepen Add Perforations Acidize		OTHER ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean out to TD @ 3880'. Deepen from 3880' to 3950'. Log well. Add additional Grayburg perforations as logs indicate. Acidize as necessary. Equip to pump. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

M. E. Abbin TITLE Staff Drilling Engineer DATE 4-10-1987
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR
DATE APR 14 1987

RECEIVED
APR 13 1987
OCD
HOBS OFFICE