

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State ☐ Fee ☒

3. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Chevron U.S.A. Inc.

Address of Operator

P.O. Box 670 Hobbs, NM 88240

Location of Well

UNIT LETTER I, 1980 FEET FROM THE South LINE AND 660 FEET FROM

THE East LINE, SECTION 10 TOWNSHIP 21S RANGE 36E NMPM.

7. Unit Agreement Name
Eunice Monument
South Unit

8. Farm or Lease Name

9. Well No.

315

10. Field and Pool, or Wildcat
Eunice Monument G/SA

15. Elevation (Show whether DF, RT, CR, etc.)
3599 GE

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

PERMANENTLY ABANDON ☐

OR ALTER CASING ☐

CHANGE PLANS ☐

OTHER Deepen Add Perforations Acidize ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean out: to TD @ 3890'. Deepen from 3890' to 3925'. Log well. Add additional Grayburg perforations as logs indicate. Acidize as necessary. Equip to pump. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

M. E. Atkins

TITLE Staff Drilling Engineer

DATE 4-10-1987

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

SIGNED BY _____

TITLE _____

DATE APR 14 1987

REMARKS OF APPROVAL, IF ANY: