

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-72

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease  
State ☐ Fee ☒  
3. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL ☒ GAS ☐ OTHER-

Name of Operator

Chevron U.S.A. Inc.

Address of Operator

P.O. Box 670 Hobbs, NM 88240

Location of Well

UNIT LETTER G 1980 FEET FROM THE North LINE AND 1960 FEET FROM  
East LINE, SECTION 10 TOWNSHIP 21S RANGE 36E NMPM.

7. Unit Agreement Name  
Eunice Monument  
South Unit

8. Farm or Lease Name

9. Well No.

304

10. Field and Pool, or Wildcat  
Eunice Monument G/SA

15. Elevation (Show whether DF, RT, GR, etc.)

3587 GE

12. County  
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

PERMANENTLY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOBS ☐

OTHER Deepen Add Perforations Acidize ☒

OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean out to TD @ 3890'. Deepen from 3890' to 3935'. Log well. Add additional Grayburg perforations as logs indicate. Acidize as necessary. Equip to pump. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Staff Drilling Engineer

DATE 4-10-1987

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

TITLE

DATE

APR 14 1987