

CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	CAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>	7. Unit Agreement Name Eunice Monument S. Uni
Name of Operator Chevron U.S.A. Inc.			8. Farm or Lease Name
Address of Operator P.O. Box 670 Hobbs, NM 88240			9. Well No. 309
Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> NMPM.			10. Field and Pool, or Allotment Eunice Monument C/SA
15. Elevation (Show whether DF, RT, GR, etc.) 3553			12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:ORM REMEDIAL WORK ☐
PERMANENTLY ABANDON ☐
OR ALTER CASING ☐PLUG AND ABANDON ☐
CHANGE PLANS ☐OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIATION WORK ☐
COMMENCE DRILLING OPS. ☐
CASING TEST AND CEMENT JOBS ☐ALTERING CASING ☐
PLUG AND ABANDONMENT ☐OTHER sqz, perf, acdz ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 3915 PB: 3782 Work performed 2-6-88 through 2-14-88

POOH w/production equipment. Set cement retainer at 3638'. Pmp 20 bbls 9# CKF thru rtmr, test tbg to 2000psi, test csg to 1000psi, establish rate thru rtmr at 3BPM w/240psi. Sqz perfs f/3702-3846 70 holes in zones 2-5, w/250sx C. Lead w/100sx C and tail w/150sx C. Start staged sqz w/60 sx. Displace w/5bbls FW. Stung out, left 9sx in csg below rtmr. put 205 sx in form. GIH, tag at 3628', drill 10' cement above rtmr, drill 8" of rtmr f/3638-3639, drlg on rtmr f/3639 to 3650'. Drill cmt f/3650' - 3780', circ hole clean, tst sqz to 500# f/30 min, held ok. Displace hole w/ CKF. POOH w/ WS. Run GR f/3768 - 3300', Drlg cmt f/3780 to 3794, circ hole and test sqz to 500#. RU welex and perf 4" csg w/ 2 7/8" guns 1 JHPF. 180° phasing, 3701 - 18, 3732-36, 3746-52, 3760-68, 34 holes. Acidize w/1700 gallons 15% NEFE HCL dropping 50 1.1 RCNB's in 1st 1400 gallons, swab. TIH w/2 1/16" tbg, ET at 3762', SN at 3725'. Turn over to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

, M. E. O'Brien TITLE Staff Drilling Engr. DATE Feb. 19, 1988ORIGINAL SIGNED BY JERRY SEXTON
ED BY DISTRICT 1 SUPERVISOR
CTIONS OF APPROVAL, IF ANY:TITLE _____ DATE FEB 24 1988

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name Eunice Monument S. Unit
Name of Operator Chevron U.S.A. Inc.		8. Farm or Lease Name
Address of Operator P.O. Box 670 Hobbs, NM 88240		9. Well No. 309
Location of Well UNIT LETTER <u>H</u> 1980 FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or WHDCat Eunice Monument G/SA
15. Elevation (Show whether DF, RT, GR, etc.) 3553		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
PERMANENTLY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Sqz, perf, acdz

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to squeeze off Grayburg zones 2-5 in order to shut off water production and reperforate zones 2 - 3 w/ 2 1/8 or 2 7/8" guns 1 SPF, 180° phase at 3702-3718, 3732-3736, 3746-3752, 3760-3768, (34 holes) Acidize 3768-3702 w/ 1700 gallons 15% NEFE HCL, swab back residue, TIH w/ production equipment and turn over to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

J. H. Smith Jr. M.E.A. TITLE: Staff Drilling Engineer DATE: February 1, 1988

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

FILED BY: _____ TITLE: _____ DATE: FEB 3 - 1988

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 2 1988

OFFICE
HARRIS OFFICE