

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
BOLE, NEW MEXICO 88240

SUBMIT IN TRIP
(Other: instruction
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒	5. LEASE DESIGNATION AND SERIAL NO. LC-032099(B)
2. NAME OF OPERATOR CONOCO INC.	6. IF INDIAN, ALLOTTEE OF TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit D	8. FARM OR LEASE NAME Lockhart B
14. PERMIT NO. 30-025-04625	9. WELL NO. 7
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 330' FNL & 330' FWL	10. FIELD AND POOL, OR WILDCAT Eumont Queen Gas
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 13 -215-36E
	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) convert to useable wellbore

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRR, POOH w/ tbg
- ② Run bit & scraper to PBTD (3705') Set pkr @ 3333'
- ③ Break down Eumont perms from 3433'-3679' w/ 100 bbls 10 lb/gal brine
- ④ POOH w/ pkr, Set retainer @ 3405'
- ⑤ Sgz Eumont perms w/ 150 sxs class "C" w/ 2% CaCl₂; flush tbg w/ 19 bbls fresh wtr. WOC 12 hrs.
- ⑥ Drill up retainer @ 3405' & cmt to 3705'. Rest sgz to 500 psi. Resgz if necessary.
- ⑦ Drill up CIBP @ 3705'. Circ. hole clean. Rig down
- ⑧ This well will be turned over to Chevron as part of the Eumont Monument South Agreement.

18. I hereby certify that the foregoing is true and correct

SIGNED DE FINNEY

TITLE Administrative Supervisor

DATE 12-2-86

(This space for field or State office use)

APPROVED BY

TITLE

DATE 12-6-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side