

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/> Federal	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Injector</u>		7. Unit Agreement Name
Name of Operator		8. Farm or Lease Name
<u>Chevron U.S.A. Inc.</u>		
Address of Operator		9. Well No.
<u>P.O. Box 670, Hobbs, NM 88240</u>		<u>396</u>
Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM		<u>Eunice Monument G/SA</u>
THE <u>West</u> LINE, SECTION <u>14</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
<u>3577' GL</u>		<u>Lea</u>

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <u>Deepen, log, acidz, convert to injector</u> <input checked="" type="checkbox"/>		OTHER <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Deepen well from TD of 3877 to 4000. Log, acidize as necessary.
Equip for injection. Test casing, pkr and tbq to 600psi for 30 min.

**Note: Federal permit (copy) attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. E. Abkin TITLE STAFF DRILLING ENGINEER DATE MAY 22, 1987

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT 1 SUPERVISOR DATE MAY 27 1987

ADDITIONAL APPROVAL, IF ANY: