

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

Form C-103
Revised 1-1-89

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer Dd. Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)
30-025-04648
6. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
8. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name EUNICE MONUMENT SOUTH UNIT
8. Well No. 428
9. Pool name or Wildcat EUNICE MONUMENT

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator CHEVRON U.S.A. INC.
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE	4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>15</u> Township <u>21 SOUTH</u> Range <u>36E</u> NMPM <u>LEA</u> County
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3574' GL	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

WORK STARTED 1/17/94.
MIRU PU, ND WH, NU BOP. PUMP 400 GALS ACID DN TBG. WORK STUCK TBG CAME FREE.
ACDZ PERFS W/2500 GALS 15% NEFE HCL. FLOW/SWAB BACK LOAD. ND BOP, NU WH.
RD PU, TURN WELL OVER TO PRODUCTION 01/24/94.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE <u>Wendi Kingston</u>	TITLE <u>TECH. ASSISTANT</u>	DATE: <u>04/12/94</u>	
TYPE OR PRINT NAME <u>WENDI KINGSTON</u>		TELEPHONE NO. <u>(915)687-7436</u>	
ORIGINAL SIGNED BY JERRY SEXTON			
APPROVED BY <u>Wendi Kingston</u>	TITLE <u>DISTRICT I SUPERVISOR</u>	DATE <u>APR 14 1994</u>	
CONDITIONS OF APPROVAL, IF ANY:			