B4. 4/ 10-108 STEELVER	VT CCONSERVATION	LDIVISION		
OISTRIBUTION		DIVISION	. Form C-103 -	
			Revised 10-1-78	
ILE	SANTA FE, NEW MEXI	CO 87501		
J.S.G.S.			5a. Indicate Type of Lease	
AND OFFICE			State X Foe	
PERATOR	•		5, State Oil & Gas Lease No.	
	Y NOTICES AND REPORTS ON WELLS			
[] 6A8 []			7. Unit Agreement Name	
well well other- Injector			↓Eunice Monument South U	
Chevron U.S.A. Inc	•		8. Form or Lease Name	
as of Operator			9. Well No.	
P.O. Box 670 Hobbs, NM 88240			422	
ition of Well			10. Field and Pool, or Wildcat	
N 60	60 PEET FROM THE SOUTH LINE	1980	Eunice Monument G/SA	
West LINE, SECTION	1/ 210	36E		
	15. Elevation (Show whether DF, RT, 3636 GL	GR, esc.)	12. County Lea	
Check A	Appropriate Box To Indicate Nature of	of Notice, Report or O	ther Data	
NOTICE OF IN		•	NT REPORT OF:	
EM REMEDIAL WORK	PLUG AND ABANDON REMEDS	AL WORK	ALTERING CASING	
Ħ	-1	=		
RAPILY ABANDON		TEST AND CEMENT JOS	PLUG AND ABANDONMENT	
Deepen and convert	to injection [X]	ER		
	K-7766			
cribe Proposed or Completed Op	erations (Clearly state all pertinent details, and	give pertinent dates, includir	ng estimated date of starting any proposed	
	72.0	man I Had		
Clean out to ID @	39/2. Deepen well from 3	712 to 7036	_'. Log well.	
Add additional Gra	yburg perforations as logs ind	nicate. Acidize as	s necessary.	
Equip for injection Return to producti	n. Test casing, packer, and toon as an injector.	ubing to 500 psi f	for 30 minutes.	
	• •			
			•	
	_			
_	·			
•	•			
	•			

hereby certify that the information above is true and comple	te to the best of my knowledge and belief.	·
· Atmille	Division Drilling Manager	9-9-1986
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	TITLE	- OATE SEP 1 1 1984

Received 1086