PGY DOMINERALS DEPAR		-~			-		
	01:	ONSERVA	TION DIVISION				
POITUBIRTE	Ī	P. O. BQ X	2088				:-103 :d 10-1-78
SANTA FE	<u> </u>	ANTA FE, NEW	MEXICO 87501			KEA126	10-1-78
FILE				Г	Sa. Indicate T	ype of Lease	
J.2.0.2.U	 			1	State X		Fee
LAND OFFICE	4		•	}	5. State Off &	Gas Legge N	
OPERATOR	1			ļ	3. 3.4.0 01. 4	043 E1430 N	•
IDO NOT USE THIS FORM FO	NDRY NOTICES A	ND REPORTS ON	ACK TO A DIFFERENT RESERVOIR				
					7. Unit Agreen	nent Name	
OIL X GAS WELL	THER-				Eunice Mo	onument S	South Un
me at Operator						ase Name	
Chevron U.S.A.	Inc.				•		
dreas of Operator		·			9. Well No.		
P.O. Box 670	Hobbs, NM 882	40			381		
cation of Weil					10. Field and	Pool, or Wild	cat
E	1980	North	660		Eunice M		
URIT LETTER			LINE AND	FEET FROM	~~~~~~	~~~~~	· · · · · · · · · · · · · · · · · · ·
West	16	21S	36E				
	3 ECTION		RANGE	НМРМ.			
	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~				7777777	7777777	4444
15. Elevation (Show whether DF, RT, GR, etc.)					12. County		
	11111111 36	19' GL			Lea		777777
Ch	eck Appropriate E	Box To Indicate N	ature of Notice, Repo	ert or Oth	er Data		
NOTICE	OF INTENTION TO	):	SUBS	EQUENT	REPORT C	)F:	
ORM REMEDIAL WORK		PLUG AND ABAHDON	REMEDIAL WORK		AL	TERING CASING	: 🔟
PORARILY ABANDON			COMMENCE ORILLING OPHS.		PCI	UG AND ABANDO	MMENT
OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT JO	ع			
_			OTHER				
Add Perforati	ions and Acidiz	:e 🔲 🗓					
	ted Operations (Clearly	state all pertinent det	tils, and give pertinent dates	, including	estimated date	of starting ar	ry proposed
pork) SEE RULE 1103.	•				•		
Add nerforat	ions from $3782^{\circ}$	- 4054'. Aci	dize as necessary.	Equip	to pump.		
Add periorde	3.13 11 3.11 37 OE			, ,			

Return to production.

Manita	Divsion Drilling Manager	9-15-1986
nece	TITLE .	
ORIGINAL CONTRACT CASE	TV 555X <b>P</b> 000	SEP 1 7 %

Month September 1998