

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-031740(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Continental Oil Company	8. FARM OR LEASE NAME Meyer A-1
3. ADDRESS OF OPERATOR Box 460 Hobbs, New Mexico 88240	9. WELL NO. 7
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL and 1980' FEL of Sec 18	10. FIELD AND POOL, OR WILDCAT Clement Queen Gas
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3664' df
	11. SEC., T., R., M., OF BLK. AND SURVEY OR AREA Sec 18, T-215, R-36E
	12. COUNTY OR PARISH Lea
	13. STATE N. Mexico

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☒

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON\*

☐

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT\*

☐

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Perf w/ 1 1/2 spf at 3196', 3208', 11', 26', 28', 33', 42', 3262', 3304', 15', 22', 28', 42', 50', 52', 74', 76', 80', 84', 96', 3398', 3424', 30', 49', 54', 62', 85', 3493', 3505', 09', 15', 19', 27', 33', 40', 50', 55', 62', 67', 74', 86', 3593', 3600', 07', 14', 30', 44', 50', 55' and 3661' (50 shots). Treat perfs w/ 5,000 gals 15% HCL - NE acid.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Administrative Supervisor

DATE

7-31-72

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE


CONDITIONS OF APPROVAL, IF ANY:

USGS (5)

FILE

NMFL(4)

\*See Instructions on Reverse Side



RECEIVED

AUG 8 1972

OIL CONSERVATION COMM.  
HOBBS, N. M.