(Feb. 1951)	PROVED CO		Budget Bureau No. 42-R358.4. Form Approved.  Land Office
J1	UL 17 1963 <i>(sue</i>	BMIT IN TRIPLICATE)	031740 h
, <u>x</u>		NITED STATES	
A 271/10	DISTRICPERAREEM	ENT OF THE INTERIO	OR Unit£
ACTING	GEO	OLOGICAL SURVEY	<b>4</b> . }
		OLOGICAL SURVEY 43	<b>J</b> ř
	4083	الله المنظمة ا	1110 4
SUND	RY NOTICES	AND REPORTS	ON WELLS
NOTICE OF INTENTION TO DR	PILL	SUBSEQUENT REPORT OF	WATER SHUT-OFF // 10
NOTICE OF INTENTION TO CH	ANGE PLANS	SUBSEQUENT REPORT OF	SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TE	ST WATER SHUT-OFF	SUBSEQUENT REPORT OF	ALTERING CASING
NOTICE OF INTENTION TO RE			RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHE		1 11	ABANDONMENT
NOTICE OF INTENTION TO PU		SUPPLEMENTARY WELL H	STORY
NOTICE OF INTENTION TO ABO	ANDON WELL		
(	(INDICATE ABOVE BY CHECK I	MARK NATURE OF REPORT, NOTICE, OR	OTHER DATA)
		May 31.	
V 15 3.6			, 19 <b></b>
Meyer B-18		(N)	e <b>(本)</b>
Well No is	located .4799 It. h	rom line and 1789	ft. from W line of sec. 18
38/4 NW/4 Sec. :	18 21-S	36-B IMPM	()
(1/2 Sec. and Sec. No.)	(Twp.)	(Range) (Merid	ian)
NOFU	T.a	Lan.	Man a Manual and
(Field)	(Con	mty or Subdivision)	New Mexi.co (State or Territory)
The elevation of the de  (State names of and expected de  TD 3942' IM, PB 3696', 3775-3695', PAY QUEEN IN INCAPABLE OF COMBRO MANNER: SET A 20 SACK SURFACE; FILLED INTERVA EXTENDING 4' ABOVE SURF	prick floor above sea  DET  population and showing points, and  ELEV 3643 DF,  3642-3682. PRI  I AL PRODUCTION.  CEMENT PLUG PROBLES BETWEEN CEMENT  PACE WITH WELL No	level is 3643 ft.  FAILS OF WORK  waises, weights, and lengths of proper all other important proposed work)  CSQ PT 5 1/2" AT 3826  FS 3838-42, 3856-58,  PLUGGING WAS ACCOMM  1 3800 to 3640: 3 ET  WT PLUGS WITH 10 18 M  AMES AND LOCATION 1880	(State or Territory)  sed casings; indicate mudding jobs, coment-  1. 4. LIMER SET FROM  3878-82. WELL WAS SHUT- PLISHED IN THE POLLOWING  A 10 BACK CEMENT PLUG AT
The elevation of the de  (State names of and expected de  TD 3942' IM, PB 3896', 3775-3895', PAY QUEEN IN INCAPABLE OF COMPERO MANNER: SET A 20 SACK SURFACE; FILLED INTERVA EXTENDING 4' ABOVE SURF RESTORED TO ORIGINAL CO MAS LEFT IN THE HOLE.	DETAILS of work must receive approve tal Oil Genpany  Sami oe, New Mexical Piles  Berlie Will Genpany  Bani oe, New Mexical Piles  Berlie Genpany  Bani oe, New Mexical Piles  Berlie Genpany  Bani oe, New Mexical Piles  Berlie Genpany	level is 3643 ft.  FAILS OF WORK  waises, weights, and lengths of proposal other important proposed work)  C3Q PT 5 1/2" AT 3824  FS 3838-42, 3856-56,  FLUGOING WAS ACCOMM  1 3800 to 3640: 3 ET  NT PLUGS WITH 10 18 M  AMS AND LOCATION 1830  INO STARTED 5-26-63,  In writing by the Geological Survey  Lee  By	(State or Territory)  seed casings; indicate mudding jobs, comentally.  4. 4. LIMER SET FROM  3878-82. WELL WAS SHUT- PLISHED IN THE FOLLOWING  A 10 BACK CEMENT PLUC AT  UD. ERECTED 4. MARKER  RIBED THERION. LOCATION  COMP 5-27-63. ALL CASING