

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME NMFU	
2. NAME OF OPERATOR Continental Oil Company		8. FARM OR LEASE NAME Meyer B-17	
3. ADDRESS OF OPERATOR Box 460, Hobbs, N.M. 88240		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL; 660' FEL of Sec. 17		10. FIELD AND POOL, OR WILDCAT Eunice Eumont	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T-21S, R.36E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH Lee	
		13. STATE N.M.	

RECEIVED
MAY 9 1977

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) Gas	

(Note: Report results of multiple completion on Well Completion Report and Log Form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

IT IS Proposed to Temp. Abandon The Eunice-Monument Oil Zone and Produce The Eumont Queen Gas Zone Through The Tbg. The Gas Pool Production Has Dropped From 450 MCFD To 160 MCFD IN THE Past Three Months. The Gas Zone is Produced From The CSG. ANNULUS While The Shut-in Eunice Oil Zone Was Produced Through The Tbg. The Oil Zone is Depleted and Has Been Shut-in For Seven years, IT IS Proposed TO DO This Work AS Follows:

1. Kill The well with Treated Fresh Water.
2. Pull Tbg and Pkr.
3. Run cast Iron Wire Line Bridge Plug and Set AT 3730'.
4. Re-Run 1 1/2" Tbg open Ended and Set AT 3400'.
5. Swab TO Production.

18. I hereby certify that the foregoing is true and correct.

SIGNED **Wm. R. Butterfield** TITLE **ADMIN. Supv.** DATE **5-6-77**

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED
MAY 9 1977
BERNARD MOROZ
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

USGS (5), NMFU (4), File (2)

APPROVED

RECEIVED

MAY 17 1977

OL. COMM. - HON. COMM.
HOBBS, R. W.