| Oí'—: | Lie Sara Minanala and | I NI-41 D - | | | | Form | |
|--|---|---|---------------------------------|--|----------------------------|--|----------|
| Dirict I | Er جy, Minerals and | i maturai Ke | sources | TET T | API NO. | Revised March | 25, 1999 |
| 1625 N. French Dr., Hobbs, NM 87240 District II | OII CONCEDUA | יאר ואטודי. | ISIOM | | API NO. <u>30-025</u> - | -04695 | |
| District II 811 South First, Artesia, NM 87210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV South Pacheco Santa Fe, NM 87505 | | | | 5. Indicate Type of Lease STATE FEE x | | | |
| | | | | | | | |
| CUNDRY NOTICE | EO AND DEDODES ON | LINELLO | | _ | | | |
| SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC. PROPOSALS.) | | EPEN OR PLUC | | 7. Lease | e Name or I | Unit Agreement Na | ne: |
| 1. Type of Well: Oil Well Gas Well Other | | | | EUNICE MONUMENT SOUTH UNIT | | | |
| 2. Name of Operator | | | | 8. Well | No. | | |
| Chevron U.S.A. Inc. | | | | 419 | | | |
| 3. Address of Operator P.O. Box 1150 Midland, TX 79 | 702 | | | 1 | name or Wi | | |
| 4. Well Location | 702 | · | | EUNICE | MONUMENT; | GRAYBURG-SAN AND | RES |
| Unit Letter O: | 660 feet from the | SOUTH | line and | 1980 | feet fron | n the EAST | _line |
| Section 17 | Township 21 | s Range | 36E | NMPM | | County 15 | |
| | 10. Elevation (Show wh | | | | *** | County | 2 |
| | | | ···· | | Mark Same Andre | Alat milanda la da da da | |
| | ppropriate Box to Ind | icate Natur | | _ | | | |
| NOTICE OF INTE | | | | SEQUE | NT REP | ORT OF: | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | REME | DIAL WORK | | | ALTERING CASIN | 1G [|
| TEMPORARILY ABANDON | CHANGE PLANS | СОМИ | ENCE DRILL | ING OPNS | i. 🗀 | PLUG AND | |
| PULL OR ALTER CASING | MULTIPLE | CASIN | G TEST AND | | | ABANDONMENT | |
| | COMPLETION | | NT JOB | | | | |
| | | | | | | | |
| OTHER: | · · | OTHE | R: TA'D | | | | [|
| 12. Describe Proposed or Completed of starting any proposed work). Sor recompilation. | SEE RULE 1103. For Mu | e all pertinent litiple Comple | details, and g tions: Attach | wellbore o | nt dates, ind | cluding estimated d proposed completio | ate |
| 12. Describe Proposed or Completed of starting any proposed work). Sor recompilation. | Operations (Clearly state SEE RULE 1103. For Mu | e all pertinent litiple Comple | details, and g | wellbore o | nt dates, ind | cluding estimated di proposed completio | ate |
| 12. Describe Proposed or Completed of starting any proposed work). Sor recompilation. POH W/TBG. RAN CSG SCRAPER | SEE RULE 1103. For Mu | e all pertinent litiple Comple | details, and g tions: Attach | wellbore o | nt dates, ind | cluding estimated di proposed completio | ate |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MIT. | SEE RULE 1103. For Mu | e all pertinent litiple Comple | details, and g tions: Attach | wellbore o | nt dates, ind | cluding estimated diproposed completion | ate |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MIT. | SEE RULE 1103. For Mu | e all pertinent litiple Comple | details, and g tions: Attach | wellbore o | nt dates, ind | cluding estimated di proposed completio | ate |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MIT. | EEE RULE 1103. For Mu | e all pertinent iltiple Comple • @ 3750'. | details, and g tions: Attach | wellbore o | nt dates, ind | cluding estimated diproposed completion | ate |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MIT. | EEE RULE 1103. For Mu | e all pertinent iltiple Comple • @ 3750'. | details, and g tions: Attach | wellbore o | nt dates, ind | cluding estimated diproposed completion | ate |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MIT. | SEE RULE 1103. For Mu | e all pertinent iltiple Comple • @ 3750'. | details, and g tions: Attach | wellbore o | nt dates, ind | cluding estimated d | ate |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MIT. | EEE RULE 1103. For Mu | e all pertinent iltiple Comple • @ 3750'. | details, and g tions: Attach | wellbore o | nt dates, ind | cluding estimated d | ate |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MIT. TA'D 11/6/01 | This Approval Abandonment E | of Tempo | details, and g tions: Attach | wellbore of | nt dates, ind | cluding estimated d | ate |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MIT. TA'D 11/6/01 | This Approval Abandonment E | of Tempo | details, and g tions: Attach | wellbore of | nt dates, ind | cluding estimated d | ate |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MIT. TA'D 11/6/01 | This Approval Abandonment E | of Tempo | details, and g tions: Attach | wellbore of | diagram of | cluding estimated diproposed completion | ate |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MIT. TA'D 11/6/01 hereby certify that the information above is LIGNATURE J. K. Lightly | This Approval Abandonment E | of Tempo | details, and g tions: Attach | wellbore of | diagram of | ATE 12/6/01 | ate n |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MTT. TA'D 11/6/01 hereby certify that the information above is EIGNATURE J. R. RIPLEY | This Approval Abandonment E | of Tempo xpires | details, and g tions: Attach | wellbore of | diagram of | ATE 12/6/01 | ate n |
| 12. Describe Proposed or Completed of starting any proposed work). So or recompilation. POH W/TBG. RAN CSG SCRAPER RAN MIT. | This Approval Abandonment E | of Tempo | details, and g tions: Attach | wellbore of | diagram of | ATE 12/6/01 | ate n |

