

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRORATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be furnished to the Bureau of Land Management, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Roswell, New Mexico
(Place)

August 20, 1963
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Shell Oil Company Devonian-State Well No. 2 in B
(Company or Operator) (Unit)
NW NE 20 21S 36E Eumont Pool
(40-acre Subdivision) 1/4 of Sec. T. R. NMPM, Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK

(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

PROPOSED OPERATION: PB for water shut-off and fracture treat.

1. Pull rods, pump and tubing.
2. Run caliper survey from TD to 7" casing.
3. Plug back w/sand to 3915' and w/Hydromite 3915' - 3892'.
4. Dump 20-40 mesh sand on top of Hydromite to plug back 3892' - 3870'.
5. Run 4" frac tubing w/Lynes open-hole inflatable packer and set packer between 7" casing and approximately 3815', using caliper log.
6. Treat w/20,000 gallons lease crude containing 1.5# sand/gallon and Mark II Adomite.
7. Pull tubing and Lynes packer. Clean out sand to Hydromite plug.
8. Run production tubing and swab test for sand flow-back.
9. Run rods and pump and place on production.

Approved....., 19.....
Except as follows:

Approved
OIL CONSERVATION COMMISSION

By.....
Title.....

Shell Oil Company

Company or Operator

By J. D. Dusen For: R. A. Lowery

Position District Exploitation Engineer
Send Communications regarding well to:

Name Shell Oil Company

Address P. O. Box 1858, Roswell, New Mexico 88201