| Submit 3 Copies To Appropriate District Office District 1 1625 N. French Dr., Hobbs, NM 87240 District II 811 South First, Artesia, NM 87210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 2040 South Pacheco, Santa Fe, NM 87505 | Energy, Minerals and OIL CONSERVA 2040 Sou | | | 5. Indicate STA | 30–025- Type of TE | Revised March 2 - 04735 f Lease FEE | C-103 25, 1999 | |
|--|--|---------------|----------------------|----------------------------|--|---|------------------------------------|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: | | | | | 6. State Oil & Gas Lease No.7. Lease Name or Unit Agreement Name: | | | |
| Oil Well Image: Constraint of Constraint 2. Name of Operator | Other | | | EUNICE MONUMENT SOUTH UNIT | | | | |
| Chevron U.S.A. Inc. | | | | 8. Well No. | | | | |
| 3. Address of Operator | | | | <u>440</u> | | | | |
| P.O. Box 1150 Midland, TX 79702 | | | | | 9. Pool name or Wildcat | | | |
| 4. Well Location | | | | LEUNICE MO | NUMENT ; | GRAYBURG-SAN ANI | RES | |
| Unit Letter D | 660 feet from the | NORTH | _ line and | 660 | feet fron | n the WEST | _ line | |
| Section 21 | Township 21 | | 362 | NMPM | | County 157 | | |
| | 10. Elevation (Show wh | | | c.) | | | | |
| 11. Check A | ppropriate Box to Ind | licate, Natur | e of Notice. | Report or | Other 1 | Data | Harden and State of State of State | |
| | NTION TO: PLUG AND ABANDON | | | SEQUEN | | | | |
| | CHANGE PLANS | | IENCE DRILLI | NG OPNS. | | PLUG AND | | |
| PULL OR ALTER CASING | MULTIPLE COMPLETION | | G TEST AND NT JOB | | | ABANDONMENT | L_J | |
| OTHER: | | | _ | | | | | |
| | | | £ | | | | | |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

CHEVRON PROPOSES TO TA PER THE ATTACHED PROCEDURE

| I hereby certify that the information above is true and complete to the best of my knowledge and belief. | | | | | | |
|--|---------|--|---------------|------------------|--|--|
| SIGNATURE J.K. Kypley | | JULATORY O.A. | DATE_ | 3/6/01 | | |
| Type or print name J. K. RIPLEY | | | Telephone No. | | | |
| (This space for State use) | | | | (915)687-7148 | | |
| APPROVED BY Conditions of approval, if any: | _ TITLE | Rd E s <u>Strand</u> Schoolag | DATE | <u>1 8 5001.</u> | | |

February 26, 2001

EMSU # 440 API # 30-025-04735 660' FNL & 660' FWL S21, T21S, R36E, & Unit D Eunice Monument South Unit · Lea County, New Mexico

PROCEDURE TO TEMPORARILY ABANDON WELL:

Notify OCD/BLM 24 hrs prior to work commencing.

1. Verify anchors have been set & tested.

2. MIRU PU. ND WH. NU BOP.

3. TOH w/ tbg. TIH w/ 4-3/4" bit, csg scraper, & WS. Make bit trip to 3752'. POH.

4. Set CIBP @ 3732'. Dump 3 sx Class 'C' cmt on CIBP.

5. TIH w/WS to TOC. Circulate csg w/corrosion inhibited pkr fluid. TOH.

6. Perform MIT (500 PSI for 30 min.). 7. ND BOP. NU WH. RD PU.

8. Clean and clear location.

Tracy Love 687-7645

Chevron

WELL DATA SHEET



| FORM: | Grayburg | g / San Andres | DATE: | | | | |
|------------------------------|----------------|-------------------|-------------------------------|---|--|--|--|
| GL: KB: DF: | 3632' 3632' | - | STATUS: API NO: Chevno: | Producer 30-025-04735 FA 58750:01 | | | |
| Date Co | mpleted: | 12/31/35 | | | | | |
| Initial Production: | | 959 BOPD / 0 BWPD | | | | | |
| Initial Formation: | | Grayburg | | | | | |
| FROM: 3785' to 3924' / GOR 1 | | | / GOR 113 | 6 | | | |
| Completion Data | | | | | | | |

Completion Data

11/7/36 Drill to 3760'. Core 3760-3799'. Set 5-1/2" csg & core 3799-3925'. RIH w/ 2" prod tbg, landed @ 3918'. Swb well in & F/ 156 BO + 2 MMCFG in 4 hrs. Complete naturally. Subsequent Workover or Reconditioning: 7/27/44 Well dead. Install flow valves. Tst: F/ 67 BOPD + 67 BWPD 2/10/48 Well F/50BOPD + 150BWPD w/gas. Replace flow valves. F/118BOPD + 118 BWPD + gas. 7/8/50 Well f/ Wtr /outside gas. Install gas lift system. Tst: F/ 33 BOPD + 170 BWPD w/gas. 1/27/53 Well f/ 15 BO + 165 BW for Dec. '52. Install pumping unit. Tst: 55 BOPD + 46.5 MCFGPD + 164 BWPD. 5/3/54 Replace prod. tbg & rods. 12/9/65 P/4 BO + 10 BW in 10 hrs. Acdz OH w/ 500 gats 15% NeA. Test: P/67 BOPD + 178 BWPD. 8/26/69 Treat well for scale buildup. 11/6/69 Treat well for scale buildup. 11/17/70 Treat well for scale buildup. 8/20/71 Test: P/42 BOPD + 180 BWPD. Acdz w/ 500 gals 15% NeA, dbl-inhibited. A/W: P/ 96 BOPD + 245 BWPD. 10/17/72 C/O to TD. Acdz w/ 500 gals 15% NeA. Tst: 78 BOPD/ 209 BWPD.B/4: 64 BOPD/ 143 BWPD. 7/73 Fish parted tbg. C/O to TD. RTP. 10/5/73 Scale squeezed & ACDZ w/ 750 gals 15% NeA dblinhibited. Tst: 63 BO/ 182 BWPD. 7/16/74 C/O to TD. Tst: 57 BOPD/ 155 BWPD. Acdz w/ 1000 gais 15% FeA & scale trtmt. A/W: 57 BOPD/ 163 BWPD. 11/8/76 Well P/45 BOPD/ 175 BWPD. Treat well for scale/paraffin buildup. ACDZ w/ 1500 gals 15% NeFeA. A/W: 70 BOPD/ 100 BWPD. 10/78 Treat well for scale. 5/22/79 Well P/42 BOPD/ 193 BWPD. Treat well for scale buildup. P/27 BOPD/ 307 BWPD. 7/16/81 Treat well for scale buildup. 1/5/82 Treat well for scale buildup. 5/26/82 Well P/ 20 BOPD/ 109 BWPD. Treat well for scale buildup & acdz w/ 1000 gals 15% NeFe. Tst: 33 BOPD/ 118 BWPD 2/83 Scale squeezed. 6/84 Scale squeezed. 3/86 Scale squeezed. 7/29/87 COWH. Deepen from 3925' to 4072'. Log WELEX CNL-CCL-GR-CAL (3000-4072') & NSP (3778-4064'). RIH w/ prod tbg. Tst: 7 BOPD/ 4 MCFGPD/ 164 BWPD. B/4: 21 BOPD/ 90 BWPD. 1/90 Scale squeezed. 3/20/90 Tst: 10 BOPD/ 98 MCFGPD/ 169 BWPD. Replace pumping unit, tog & rods. A/W: 20 BOPD/ 76 MCFGPD/ 258 BWPD 8/90 Scale squeezed. Additional Data: T/Queen Formation @ 3550' T/Penrose Formation @ 3688' T/Grayburg Zone 1 @ 3866' T/Grayburg Zone 2 @ 3912' T/Grayburg Zone 2A @ 3963' T/Grayburg Zone 3 @ 4004' T/Grayburg Zone 4 @ 4048' T/Grayburg Zone 5 @ 4099' T/Grayburg Zone 6 @ 4135' T/San Andres Formation @ 4143' KB @ 3632'

Chevron

PROPOSED TA WELL DATA SHEL

KB @ 3632'



| FORM: | Grayburg | / San Andres | DATE: | | | |
|--|--------------------------------------|---|---------|--|--|--|
| GL: KB: DF: | 3632' 3632' | • • | API NO: | SI Producer 30-025-04735 FA 58750:01 | | |
| Initial P | empleted: roduction: ormation; | 12/31/35 959 BOPD / 0 Grayburg 3785' to 3924 | | 6 | | |
| | letion Da | | | | | |
| 11/7/36 Drill to 3760'. Core 3760-3799'. Set 5-1/2" csg & core 3799-3925'. RIH w/ 2" prod tbg, landed @ 3918'. Swb well in & F/ 156 BO + 2 MMCFG in 4 hrs. Complete naturally. | | | | | | |
| Subsequent Workover or Reconditioning: | | | | | | |
| 7/27/44 Well dead. Install flow valves. Tst: F/ 67 BOPD + 67 BWPD. | | | | | | |

IB۱ 2/10/48 Well F/50BOPD + 150BWPD w/gas. Replace flow valves. F/118BOPD + 118 BWPD + gas. 7/8/50 Well f/ Wtr /outside gas. Install gas lift system. Tst: F/ 33 BOPD + 170 BWPD w/gas. 1/27/53 Well f/ 15 BO + 165 BW for Dec. '52. Install pumping unit. Tst: 55 BOPD + 46.5 MCFGPD + 164 BWPD. 5/3/54 Replace prod. tbg & rods. 12/9/65 P/4 BO + 10 BW in 10 hrs. Acdz OH w/ 500 gals 15% NeA. Test: P/67 BOPD + 178 BWPD. 8/26/69 Treat well for scale buildup. 11/6/69 Treat well for scale buildup. 11/17/70 Treat well for scale buildup. 8/20/71 Test: P/42 BOPD + 180 BWPD. Acdz w/ 500 gais 15% NeA, dbl-inhibited. A/W: P/ 96 BOPD + 245 BWPD. 10/17/72 C/O to TD. Acdz w/ 500 gais 15% NeA. Tst: 78 BOPD/ 209 BWPD.B/4: 64 BOPD/ 143 BWPD. 7/73 Fish parted tbg. C/O to TD. RTP. 10/5/73 Scale squeezed & ACDZ w/ 750 gals 15% NeA dbiinhibited. Tst: 63 BO/ 182 BWPD. 7/16/74 C/O to TD. Tst: 57 BOPD/ 155 BWPD. Acdz w/ 1000 gals 15% FeA & scale trtmt. A/W: 57 BOPD/ 163 BWPD. 11/8/76 Well P/45 BOPD/ 175 BWPD. Treat well for scale/paraffin buildup. ACDZ w/ 1500 gals 15% NeFeA. A/W: 70 BOPD/ 100 BWPD. 10/78 Treat well for scale. 5/22/79 Well P/42 BOPD/ 193 BWPD. Treat well for scale buildup. P/27 BOPD/ 307 BWPD. 7/16/81 Treat well for scale buildup. 1/5/82 Treat well for scale buildup. 5/26/82 Well P/ 20 BOPD/ 109 BWPD. Treat well for scale buildup & acdz w/ 1000 gals 15% NeFe. Tst: 33 BOPD/ 118 BWPD. 2/83 Scale squeezed. 6/84 Scale squeezed. 3/86 Scale squeezed. 7/29/87 COWH. Deepen from 3925' to 4072'. Log WELEX CNL-CCL-GR-CAL (3000-4072') & NSP (3778-4064'). RIH w/ prod tbg. Tst: 7 BOPD/ 4 MCFGPD/ 164 BWPD, B/4; 21 BOPD/ 90 BWPD. 1/90 Scale squeezed. 3/20/90 Tst: 10 BOPD/ 98 MCFGPD/ 169 BWPD. Replace pumping unit, tbg & rods. A/W: 20 BOPD/ 76 MCFGPD/ 258 BWPD. 8/90 Scale squeezed. Additional Data: T/Queen Formation @ 3550' T/Penrose Formation @ 3688' T/Grayburg Zone 1 @ 3866' T/Grayburg Zone 2 @ 3912' T/Grayburg Zone 2A @ 3963' T/Grayburg Zone 3 @ 4004' T/Grayburg Zone 4 @ 4048' T/Grayburg Zone 5 @ 4099' T/Grayburg Zone 6 @ 4135' T/San Andres Formation @ 4143'

printed: 2/26/2001