

NO. OF COPIES REQUIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPERATE OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.

30. Indicate Type of Lease
State ☒ Fee ☐

31. State Oil & Gas Lease No.
B-229

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER

7. Unit Agreement Name

12. Name of Operator

8. Term of Lease (gms)

13. Address of Operator

Wright Limonay, OCT-C

P. O. Box 670, Hobbs, NM 88240

9. Well No.
6

14. Location of Well

10. Field and Name, or Wildcat

UNIT LETTER *C* *666* FEET FROM THE *North* LINE AND *1980* FEET FROM THE *West* LINE, SECTION *21* TOWNSHIP *21S* RANGE *36E* WPM.

Quinn Monument

15. Elevation (Show whether DF, KT, GR, etc.)

12. County

3620' GL

Lia

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Oil well.
POH w/ thg. tag. TD @ 5906'. Let RBP @ 3730'. Let csg. 500# - OK.
POH w/ RBP. Work performed 3-12-85. Csg valves inspected by Eddie Ray w/ O.C.D.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Jerry Sexton for AREA ENGINEER *3-22-85*

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

MAR 26 1985