

CONSERVATION DIVISION

P. O. BOX 2038

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
 State Fee
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER-
 7. Unit Agreement Name

Name of Operator
 Chevron U.S.A. Inc.
 8. Farm or Lease Name Unit

Address of Operator
 P. O. Box 670, Hobbs, NM 88240
 9. Well No. 443

Location of Well
 UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM
 10. Fluid and Pool, or Wildcat Eunie Monument G/SA

THE East LINE, SECTION 21 TOWNSHIP 21S RANGE 36E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
 3609
 12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING
 TEMPORILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
 REPAIR OR ALTER CASING OTHER CASING TEST AND CEMENT JOB OTHER Deepen, Log, Acidize
 OTHER

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4032'
 POH with rods, pump and liner. Clean out fill 3856' to 3896'. Drill and clean out hydromite sand plug 3896-3902'. Drill 3904' to 4032'. Log with CNL-GR-CCL & CAL, 2 repeats TD to 3700', main pass TD to surface. RIH with production tubing, pump and rods. Hang well on, test pump tubing to 500 psi-ok.
 Work performed 6-29-87 through 7-5-87.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

M. E. Abbin TITLE Staff Drilling Engineer DATE 10-20-87

ORIGINAL SIGNED BY JERRY SEXTON
 DISTRICT I SUPERVISOR

TITLE DATE 10 22 1987