

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Field or Lease Name J.M. Brownlee
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201		9. Well No. 2
4. Location of Well UNIT LETTER M 330 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 21-S RANGE 36-E NMPM.		10. Field and Pool, or Wildcat Arrowhead-Grayburg
15. Elevation (Show whether DF, RT, GR, etc.) 3515' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged & abandoned in the following manner:
Killed well w/80 bbls brine water. Spotted 30 sk cement plug 3530-3740'. Attempted to load hole w/50 BW after 40 hrs WOC. Unable to load hole. Spotted 30 sk cement plug 3530-3740'. Attempted to load hole w/50 bbls brine water, unable to load hole. Set 5½" 17# Titan CIBP @ 3670', capped w/5 sx cement (35'). Shot off 5½" casing at 1047'. Pulled 23 jts (1041.95') 5½" OD 8R 17# J-55 ST&C casing. Spotted 40 sk cement plug 1155-975'; 40 sk cement plug 370-254'; 10 sk cement plug in top of well. Erected dry hole marker. Well P & A 4/13/72. Salt gel mud was used to spot all plugs. 8-5/8" casing remains intact.

Your office will be notified when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D.L. Butcher TITLE Dist. Drlg. Supervisor DATE 4/19/72

APPROVED Nathan E. Clegg TITLE OIL & GAS INSPECTOR DATE 5 1973
CONDITIONS OF APPROVAL, IF ANY: