

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04785
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B 935
7. Lease Name or Unit Agreement Name	New Mexico "G" State
8. Well No.	10
9. Pool name or Wildcat	Eumont Yates Seven Rivers

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Exxon Corporation	3. Address of Operator P. O. Box 1600, Midland, TX 79702	4. Well Location Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line Section 26 Township 21S Range 36E NMMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3545' DF
---	--	---	---	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-29-91 Plug 1 3762 - 3257 Set CIBP at 3762', circ 9.5 brine, pump
30 sx Cl C cement
Plug 2 1588 - 1083, 30 sx Cl C cement, circ brine to surface.
10-30-91 Plug 3 380 - Surf, Perfed 4 squeeze holes at 380', circ 9.5 brine,
136 sx Cl C, circulated to surface.

Welded on dry hole marker. Cleaned location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Judy Bagwell TITLE Sr Staff Office Assistant DATE 11/26/91
(915)
TYPE OR PRINT NAME Judy Bagwell TELEPHONE NO. 688-7546

(This space for State Use)

APPROVED BY Carly M. Hill TITLE OIL & GAS DATE JAN 03 '92
CONDITIONS OF APPROVAL, IF ANY: