

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-88

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		API NO. (assigned by OCD on New Wells)
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator CHEVRON U.S.A. INC.		6. State Oil & Gas Lease No. B-1732
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS		7. Lease Name or Unit Agreement Name W.A. RAMSAY (NCT-A)
4. Well Location Unit Letter M : 660 Feet From Th SOUTH Line and 660 Feet From The WEST Line Section 27 Township 21S Range 36E NMPM LEA County		8. Well No. 2
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3586' GL		9. Pool name or Wildcat EUMONT

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTER CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABAN. <input type="checkbox"/> CASING TEST AND CMT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

IT IS PROPOSED TO: PLUG AND ABANDON WELL
TIH WITH CIBP AND SET AT 3725', LOAD HOLE WITH FLUID AND TEST CASING.
SPOT 105' CMT ON TOP OF CIBP. PLUG WILL COVER QUEEN PAY.
SET 250' BALANCED PLUG FROM 3135-3385, PLUG COVERS YATES & 7-RIVERS.
PERF AT 1715', BREAK CIRC BETWEEN 5.5" & 7 5/8" CSG. SET CIRC AT 1515'.
PUMP 150 SXs. CMT INTO CIRC, PULL OUT AND LEAVE 35' CMT ON TOP.
ABOVE PLUG WILL COVER RUSTLER AND SALT FORMATIONS.
SET A 10 SX. PLUG FROM SURFACE TO 100'.
CUT OFF WELLHEAD AND INSTALL P & A MARKER.
10# P & A MUD WILL BE PLACED BETWEEN ALL CMT. PLUGS.
CHANGE WELL STATUS TO P & A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	<i>P.R. Matthews</i>	TITLE	TECH. ASSISTANT	DATE:	5/20/92
TYPE OR PRINT NAME	P.R. MATTHEWS			TELEPHONE NO	(915)687-7312

APPROVED BY _____ TITLE _____ DATE MAY 22 '92
CONDITIONS OF APPROVAL, IF ANY: _____