

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer 66, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

Santa Fe, New Mexico 87504-2088

API NO. (assigned by OCD on New Wells) 30-025-04796	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. B-1732	
7. Lease Name or Unit Agreement Name W. A. RAMSAY (NCT-A)	
8. Well No. 31	
9. Pool name or Wildcat EUMONT	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: WENDI KINGSTON	
4. Well Location Unit Letter 0 : 660 Feet From The SOUTH Line and Section 27 Township 21S Range 36E NMPM 1980 Feet From The EAST Line LEA County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3565' GL	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTER CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO PLUG AND ABANDON THIS WELL AS FOLLOWS:
PLUG #1, SET CIBP AT 3725' AND SET 5 SX CMT ON TOP.
PLUG #2, PERF & SQZ 40 SX PLUG FROM 1558'-1658', COVERS SALT ZONE.
PLUG #3, PERF & SQZ 40 SX PLUG FROM 350'-450', COVERING 8 5/8" SHOE.
PLUG #4, PERF & SQZ 35 SX PLUG FROM 50'-SURFACE.
ALL PLUGS ARE CLASS C NEAT MIXED AT 14.8 PPG, 1.32 CU/FT SX. DISPLACE
HOLE W/9.5 PPG MUD LADEN FLUID. PULL DEAD MAN ANCHORS, FILL PITS, LEVEL LOCATION,
PLACE P&A MARKER & CHANGE STATUS OF WELL TO P&A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wendi Kingston TITLE TECH. ASSISTANT

DATE: 10/27/94

TYPE OR PRINT NAME WENDI KINGSTON

TELEPHONE NO. (915)687-7826

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

DATE OCT 31 1994