

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

NEW MEXICO OIL CONSERVATION COMMISSION

JAN 17 1967

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|  |
|--|
| 5a. Indicate Type of Lease<br>State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.<br><b>B-1732</b>  |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|   |  |
|---|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>   | 7. Unit Agreement Name                               |
| 2. Name of Operator<br><b>Gulf Oil Corporation</b>  | 8. Farm or Lease Name<br><b>W. A. Ramsay (NCT-A)</b> |
| 3. Address of Operator<br><b>Box 670, Hobbs, New Mexico</b>   | 9. Well No.<br><b>40</b>                             |
| 4. Location of Well<br>UNIT LETTER <b>A</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM<br>THE <b>East</b> LINE, SECTION <b>27</b> TOWNSHIP <b>21-S</b> RANGE <b>36-E</b> NMPM. | 10. Field and Pool, or Wildcat<br><b>Bumont</b>      |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br><b>3552' GL</b>  | 12. County<br><b>Lea</b>                             |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|  |   |   |   |
|--|---|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>            | CASING TEST AND CEMENT JOB <input type="checkbox"/> |   |
| OTHER <input type="checkbox"/>                 |   | <b>Cleaned out and acidized</b>                     |   |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**3915' PB.**

Killed well with 25 barrels of oil. Pulled 2-3/8" tubing and full bore packer. Cleaned out with 3-1/2" sand pump from 3902' to 3915'. Ran 128 joints, 3891' of 2-3/8" tubing with PCOB set at 3901', SN at 3890'. Spotted 100 gallons of 15% NE acid over 5-1/2" casing perforations 3738' to 3910'. Let set 30 minutes. Pumped 900 gallons of 15% NE acid down tubing. IR 6 bpm at 1300 - 1500#. Left acid on formation 2 hours. Flushed with 15 barrels of oil. Swabbed and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED \_\_\_\_\_ TITLE **Area Production Manager** DATE **January 16, 1967**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: