NO. OF COPIES RECEIVED					Form C-103
DISTRIBUTION			=		Supersedes Old C-102 and C-103
ANTA FE	NE	W MEXICO OIL CONSE	RUNDERBERNA	VISSION C. C.	Effective 1-1-65
ILE					
S.G.S.			APR 5 3	32 PM '66	5a. Indicate Type of Lease
AND OFFICE					State 🛣 Fee
PERATOR					5, State Cil & Gas Leuse No.
				 	B-1732
(DO NOT USE THIS FORM	SUNDRY NOTICES	AND REPORTS ON W	VELLS	RESERVCIR.	
		200 (FORM C-101) FOR SUCH	PROFUSALS.	, <u>.</u> ,	7. Unit Agreement Name
OIL WELL GAS WELL Name of Operator	OTHER-				8. Farm or Lease Name
Oulf Oil Corpora	tion				W. A. Ransay (NCT-A)
Address of Operator Box 670, Hobbs,	New Mexico				4.7
Location of Well		Cauti	460		10. Field and Pool, or Wildow
		FROM THE South			
THE West	HE, SECTION 27	TOW-SHIP 21-5	RANGE	36-E	
	15.	Elevatic:: (Show whether D			12. County
			3567' GL		Les ()
	Check Appropriate E OF INTENTION	Box To Indicate Na	ature of Notic		Other Data NT REPORT OF:
110110					·
REPORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
			COMMENCE DRILLI		ALTERING CASING
EMPORAPILY ABANDON					i i
EMPORARILY ABANDON			COMMENCE DRILLI	CEMENT JOB	i i
emporarily abandon LLL OF ALTER CASING OTHER 7. I-Honorice Proposed or Com nork) SEE RULE 1103.	pleted Operations (Clea	CHANGE PLANS	CASING TEST AND OTHER	cement JQB	i i
OTHER . Newstare Proposed or Community SEE RULE 1103.		CHANSE PLANS	COMMENCE DRILLI CASING TEST AND OTHER CI Re ils, and give perti	port	PLUG AND ABANDONMENT
OTHER	nformation above is true	n. No plans hav	CASING TEST AND OTHER CI Re ils, and give perti	port nent dates, includ e at this t	PLUG AND ABANDONMENT