

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator <b>Humble Oil &amp; Refining Company</b>		8. Farm or Lease Name <b>New Mexico "B" St.</b>	
3. Address of Operator <b>c/o Hobbs Pipe &amp; Supply Company, Box 2010, Hobbs, N.M.</b>		9. Well No. <b>3</b> <i>APZ</i>	
4. Location of Well UNIT LETTER <b>J</b> , <b>1980</b> FEET FROM THE <b>East</b> LINE AND <b>1980</b> FEET FROM THE <b>South</b> LINE, SECTION <b>29</b> TOWNSHIP <b>21-S</b> RANGE <b>36-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Eumont</b>	
15. Elevation (Show whether DF, RT, GR, etc.) <b>3631' D.F.</b>		12. County <b>Lea</b>	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 50 sx cement plug from 3700'-3880'.
2. Spotted a 10 sx cement plug from 0' - 50'.
3. Hole was loaded with mud laden fluids.
4. Well was plugged and abandoned on 11-3-70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>[Signature]</i>	TITLE <b>Agent</b>	DATE <b>12/3/70</b>
APPROVED BY <i>[Signature]</i>	TITLE <b>Geologist</b>	DATE <b>JUL 19 1971</b>
CONDITIONS OF APPROVAL, IF ANY:		