

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501Form C-103
Revised 10-1-77

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator EXXON CORPORATION	8. Farm or Lease Name NEW MEXICO "B" STATE
3. Address of Operator Box 1600, MIDLAND, TEXAS 79702	9. Well No. 8
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>660</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>29</u> TOWNSHIP <u>21-S</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat EUMONT OIL
15. Elevation (Show whether DF, RT, GR, etc.) 3625 R.T.	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	
OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. PULL RODS AND TUBING
2. BAIL OUT FILL TO TD (3865')
3. FIRE A 300 GRAIN STRING SHOT FOLLOWED BY A 500 GRAIN SHOT IN OH 3799-3865.
4. ACIDIZE W/6600 GAL 15% INHIBITED NEHCL.
5. SWAB BACK LOAD AND TEST PRODUCTION.
6. PLACE WELL ON PUMP.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. A. Lowe TITLE SR ADMIN DATE 6-4-84

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE _____

DATE JUN 6 1984

CONDITIONS OF APPROVAL, IF ANY: