NET PTCO OIL CONSERVATION CO. J ON

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

| | | | _ | MODICE OF INCOM | INION EO O | VOID 07: | 1 |
|-------------------------------------|---------------------------------|---|-------------------------------------|---|--|---|---------------|
| NOTICE OF INTENT | ION TO TEST O | CASING SHUT-OF | 'F I | NOTICE OF INTEN | REAT WELL | OUT OR | |
| NOTICE OF INTENTION TO CHANGE PLANS | | | | NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING | | | |
| NOTICE OF INTENTION TO REPAIR WELL | | | | NOTICE OF INTEN | TION TO PLUG | WELL | |
| NOTICE OF INTEN | TION TO DEEP | PEN WELL | | | | | - |
| | | | 164 27 2 | Marca Anni I | 14 1646 | | |
| | | | Mi diano, | Texas, April | 10, 1900 | Date | |
| OIL CONSERVATI | ON COMMISS | ION, | | | | | |
| Santa Fe, New Mer | rico. | | | | | | |
| Gentlemen: | ee of intentito | n to do contain | Work or dogowi | bed below at the | | | |
| _ | | | work as descri S tate "B" | | | in SE/ | 4 of ST |
| humble Oil & P Company or Op | erator | Le | ase | Well | | inin_ | - O. D. |
| of Sec. 29 | , т1 | 21 <u>-</u> S , R. 3 | 6-E , N. | M. P. M., | Aunice | | Field |
| Lea | | County. | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | SE | T CASING AS | FOLLOWS: | | | |
| ze weight | TRUOMA | set at | T CASING AS | FOLLOWS: TOTAL DEPTH OF WELL | NO. SACK | | |
| | AMOUNT 38 69 *5 * | | | TOTAL DEPTH OF WELL | | CEMENT | BOT 9:30 |
| 1/2" 17# | 3869 15* | SET AT 3882*2* | FORMATION Gray Lime | TOTAL DEPTH OF WELL | MAKE OF | CEMENT | BOT 9:30 |
| 1/2" 17# | 38 69 *5 * Balliburto | SET AT 3882*2* n method us | FORMATION Gray Lime | TOTAL DEPTH OF WELL 3914* | MAKE OF | 1 Toro | BOTT 9:30 |
| 1/2" 17# | 38 69 *5 * Balliburto | SET AT 3882*2* n method us | FORMATION Gray Lime | TOTAL DEPTH OF WELL | MAKE OF 200 sx. E | CEMENT Il Toro | 9:30 4/12/ |
| 1/2" 17# | 3869 %* | SET AT 3882*2* n method us | FORMATION Gray Lime | TOTAL DEPTH OF WELL 3914* | MAKE OF 200 sx. E | CEMENT Il Toro | 9:30 4/12/ |
| 1/2" 17# | 38 69 *5 * Balliburto | SET AT 3882*2* n method us | FORMATION Gray Lime ed. cold water | TOTAL DEPTH OF WELL 3914* | 200 sx. E | TOPO | 9:30 4/12/ |
| 1/2" 17# | 3869 %* | SET AT 3882*2* n method us | FORMATION Gray Lime | TOTAL DEPTH OF WELL 3914' pressure on fi | 200 sx. E | CEMENT Toro 56. | 9:30 4/12/ |
| 1/2" 17# | 3869 %* | SET AT 3882*2* n method us | FORMATION Gray Lime ed. cold water | TOTAL DEPTH OF WELL 3914' pressure on fi | MAKE OF 200 sx. E | CEMENT Toro 56. | 9:30 4/12/ |
| 1/2" 17# | 3869 %* | SET AT 3882*2* n method us | FORMATION Gray Lime ed. cold water | TOTAL DEPTH OF WELL 3914* pressure on fi | MAKE OF 200 sx. E Refining C Company or O | CEMENT Il Toro S6. Company perator | 9:30 4/12/ |
| 1/2" 17# | 3869 %* | SET AT 3882*2* n method us | FORMATION Gray Lime ed. cold water | TOTAL DEPTH OF WELL 3914 pressure on Fi Humble 011 & | MAKE OF 200 sx. E Refining C Company or O | Toro 56. Company perator | 9130 4/12/ |
| Approved except as follows: | 3869 5. | SET AT S882*2* n method us with 1200# | FORMATION Gray Lime ed. cold water | TOTAL DEPTH OF WELL 3914 pressure on Fi Humble 011 & | Refining Company or of Superinte | Toro 56. Company perator | 3 |
| Approved except as follows: | 3869 5. | SET AT 3882*2* n method us | FORMATION Gray Lime ed. cold water | TOTAL DEPTH OF WELL 3914. pressure on Fi Humble Oil & Position Division Send comm | Refining Company or O | CEMENT Toro S6. Company perator endent arding well | 9130 4/12/ |

ICR