SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	F INDIAN, ALLOTTEE OR TRIBE NAME
Use "APPLICATION FOR PERMIT—" for such proposals.)	
1. OIL GAS WELL OTHER 2. NAME OF OPERATOR 8. F	INIT AUREEMENT NAME
	ockhart B-31
P. O. Rox 460, Hobbs, ilew Hexico 88240 1. Location of Well. (Report location clearly and in accordance with any State requirements.) See also space 17 below.) At surface 1980' F51 \$ 660' FEL 11.	SEC., T., R., M., OR BLE. AND SURVEY OR AREA
5-	COUNTY OF PARISH 13. STATE LIA NM
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical department to this work.)* Status of Well: Stut Well Approximate date that temp. aban. commenced: 9-1-66 Reason for temp. aban.: Uneconomical	Report and Log form.) ding estimated date of starting any ths for all markers and zones perti-
Holding for secondary recovery This approval of temporary abandonment expires DEC 1	- 1976 -
Approximate date of future W. O. or plugging: Indefinity 18. Thereby certify that the foregoing is true and correct SIGNED S Oullinging TITLE Softman and Correct	Fe
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	DATE

USGS (5) FILE Nmga (4)

*See Instructions on Reverse Side SURVEY MEXICO