

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Late Oil Company		8. Farm or Lease Name Rector
3. Address of Operator Drawer 71, San Angelo, Texas		9. Well No. 2
4. Location of Well UNIT LETTER <u>G</u> <u>1880</u> FEET FROM THE <u>N</u> LINE AND <u>1980</u> FEET FROM THE <u>E</u> LINE, SECTION <u>31</u> TOWNSHIP <u>21S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat South Eunice
15. Elevation (Show whether DF, RT, GR, etc.) 3635 DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject depleted well plugged and abandoned work being performed on Dec. 13, 1966. Plugging performed as follows:

25 sx cement plug set at 3670'; 25 sx cement plug set at interval 1560-1460';
25 sx cement plug set 830-730' (cut-off point);
25 sx cement plug set 310-210' in and out of surface casing;
10 sx cement plug set at surface.

All equipment removed from lease, surface returned to original contour, permanent marker has been set to identify the location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>John A. Mangan</u>	TITLE <u>Agent</u>	DATE <u>January 2/68</u>
APPROVED BY <u>John W. Remyan</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		