Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Resided 1-1-39

District Office

DISTRICT] P.O. Box 1980, Hobbs, NM \$8240

DISTRICT II P.O. Drawer DD, Ariesia, NM 88210

DISTRICT 1000 Rio Brazos Rd., Aziec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088 WELL API NO. . 5. Indicate Type of Lease STATE FEE X

6. State Oil & Gas Lease No.

| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | | | | 7. Lease Name or Unit Agreement | Name | |
|---|---------------|---------|-----------------------|---------------------|---------------------------------|-------------------------|------------|
| 1. Type of Well: | GUS | OTHER : | | LT WATE SPOSAL | | Atha "M" | |
| 2. Name of Operator | | | | 01 00112 | WELL | 8. Well No. | |
| McCasland Dis | posal System | | | | | 1 | |
| 3. Address of Operator | | | | | | 9. Pool name or Wildcat | |
| | Eunice, NM 88 | 231 | | | | Jalmat Yates SF | Queen |
| 4. Well Location Unit LetterM Section 31 | Township | 225 | Ra | աթ . 361 | Ξ , | Fed From The West | County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3615 GL | | | | | | | |
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | | | | | | | |
| NOTICE OF INTENTION TO: | | | SUBSEQUENT REPORT OF: | | | | |
| PERFORM REMEDIAL WOR | K PLUG AND A | IBANDON | | REMEDIAL | WORK | ALTERING CAS | ing 🔲 |
| TEMPORARILY ABANDON | CHANGE PL | ANS | | COMMENC | E DRILLING | OPNS. PLUG AND ABA | NDONMENT [|
| PULL OR ALTER CASING | | | | CASING TE | ST AND CEN | AENT JOB X | |
| OTHER: | | | | OTHER: | · | | |

- 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
 - 1. Squeeze perfs 3511-3679' with 30 sx Class "C" cement neat.
 - 2. DOC and test squeeze to 500 psi for 30 minutes. Held OK.
 - Rerun AD-1 tension packer and 2 3/8" plastic lined tubing. 3. Set packer @ 3706'. Load backside with inhibited packer fluid.
 - Return well to injection. 4.

| | LELOC above to true and goompiete to the best of the | | 5 /1 /01 |
|----------------------------|--|----------|----------------------|
| SIGNATURE | rry & Dutt | mu Agent | DATE5/1/91 |
| TYPE OR PRINT NAME I | arry R. Scott | | ТЕДЕНОЧЕ NO 392-6950 |
| (This space for State Use) | Orig. Signed by | | 8 8 60 V 10 18 66 A |
| APTROVED BY | Paul Kautz Geologist | TOF - | MAY 5 3 199 |