

NEW MEXICO STATE LAND OFFICE.  
SANTA FE, NEW MEXICO  
DEPARTMENT OF THE STATE GEOLOGIST  
SANTA FE

### NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Bunice,, N. Mex., July 3, 1936

Mr. F. J. Vesely

Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon State "E" Well  
No. 1 in NW 1/4 of Sec. 32 Twp. 21, Rge. 36,  
N. M. P. M., Bunice Oil Field, Los, County.  
We plan to commence work on or About July 15, 1936.

The reasons for wishing to abandon the well are as follows:

**Not enough production to pay to try to lift.**

The present condition of the well is as follows:

**Pumping with 2½" tubing 5 barrels of oil with 20 barrels water.**

DUPLICATE

The work which we propose to do in abandoning the well is as follows:

**Will test well from 3737 feet to 3742 feet as per Form O 102**

**dated July 3, 1936. If no results will abandon.**

**It shall be plugged in a manner which will confine permanently all oil, gas and water separate strata originally containing them. The operation shall be accomplished by the use of mud-laden fluid, cement and plugs. Will pull all of production casing string and intermediate casing string possible, will cement up all of surface casing and well will be marked 4" marker set in concrete 4' above ground level.**

Approved JUL 9 1936 1936

Except as follows:

**General Crude Oil Company,**

Company or Operator.

By Jean Hildreth

Position Dist. Supt.

Send communications regarding this well to

Name Jesse T. Hildreth

Address Box 625, Hink, Texas.

F. J. Vesely  
State Geologist or Oil and Gas Inspector.