DISTRIBUTION NEW MEXICO OIL CONSERVATION COMMISSION FILE U.S. O.S. LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS TO STATE OF COMPLETE OF THE PROPERTY OF THE	NO. OF COPIES RECEIVED	· ·	Form C-103
SUNDRY NOTICES AND REPORTS ON WELLS OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS OPERATOR SUNDRY THE PROPERTY OF THE PROPE		4	Supersedes Old C-102 and C-103
LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS 10 NOT DET THE TOP ANALYSIS OF PRODUCT OF THE TOP SHEET PRODUC		NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
SUNDRY NOTICES AND REPORTS ON WELLS OF THE OWN OF THE POST OF THE OWN OWN OF THE OWN OWN OF THE OWN		<u> </u>	
SUNDRY NOTICES AND REPORTS ON WELLS OF NOTICE OF NOTICE OF NOTICE AND WELLS OF NOTICE OF NOTICE OF NOTICE OF NOTICE AND REPORT OF SUBSEQUENT REPORT OF S		4	F
SUNDRY NOTICES AND REPORTS ON WELLS Compared to the feether content of the feether conte		4	
SUNDER NOTICES AND REPORTS ON WELLS Control of Contr	OPERATOR]	
The control of the co	SUNDF	AY NOTICES AND REPORTS ON WELLS	
Once On Part Committee on the Committee of the Part of the Committee of the Committee of Committ		TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7 Unit Agreement Name
3. Addition of Components S. Additions S.	OIL GAS WELL	OTHER- Dual (Commingled in well bore)	
2. Additional Composition of Well Description of Well Out Letter 0 Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: CHANGE PLANS CH			
Bex 570, Nobbe, Now Marieo 88240 1. Location of Well UNIT LETTER 0 660 FEET FROM THE SORTH LINE AND 1980 FEET FROM THE SORTH LIN			
DEST LETTER O	•	eries 882h0	1.
THE BEST LINE, SECTION 32 TOWNSHIP 21-S HARGE 36-E NAME 12, COUNTY 15, Elevation (Show whether DF, RT, CR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: THE MODARILY ADARDON PULIC AND ABADDON NEMEDIAL WORK PLUG AND ABADDON NEMEDIAL WORK		ATSS COSTC	10. Field and Pool, or Wildcat
THE Best LINE, SECTION 32 TOWNSETP 21-5 HARGE 36-E HAPPIN 12, COUNTY 15, Elevation (Show whether DF, RT, CR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABADDON REMORAL WORK PLUG AND ABADDON PLUG AND ABADDON REMORAL WORK PLUG AND ABADDON PL	UNIT LETTERO	660 FEET FROM THE South LINE AND 1980 FEET	Jalmat & South Bunice
15. Elevation (Show whether BE, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM MEMEDIAL WORK PULL OR ALTERING CASING OTHER 17. Descrip Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting tray proposed work) SEE RULE 1103. 3875: PB. Pulled rods and pump. Pumped 500 gallons of 155 NB sold down 5-1/2" casing over Jalmat perforations 3396: to 3411' and South Bunice perforations 3778 to 3856'. Flushed with 17 barrels of fresh water. Ren rods and pump and returned well to production. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL Signed ST. C. D. BORLAND THEE Area Production Manager OATE APRIL 7, 1970 APRIL 337	,		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUS AND ABANDON PULL ON ALTERIAG EASING OTHER OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated dais of starting may proposed work) SEE RULE 1103. 3875 ' PB. Pulled rods and pump. Pumped 500 gallons of 15% NB soid down 5-1/2" casing over Jalmat perforations 3396' to 3411' and South Bunice perforations 3778 to 3856'. Plushed with 17 barrels of fresh water. Ran rods and pump and returned well to production. OTHER STAND OTHER STANDARD THE ARCHITICAL STAND	THE LINE, SECTI	10N 32 TOWNSHIP 21-5 RANGE 36-K N	MPM. (())
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUG AND ABANDON PULU OR ANTER CASING PULU OR ANTER CASING OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see Rule 1703. 3875' PB. Pulled rods and pump. Pumped 500 gallons of 15% NR soid down 5-1/2" casing over Jalmat perforations 3396' to 3411' and South Bunice perforations 3778 to 3856'. Plushed with 17 barrels of fresh water. Ran rods and pump and returned well to production. Office April 7, 1970 C. D. BORLAND THEE Area Production Manager OATE April 7, 1970 APRIL 1377			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: NEMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASIN PLUG AND ABANDON ALTERING CASIN ALTERING CASIN PLUG AND ABANDON ALTERING CASIN ALTERING CASIN PLUG AND ABANDON ALTERING COMMENT ALTERING CASIN ALTERING CA			12. County
NOTICE OF INTENTION TO: PERFORM MEMEDIAL WORK		3614' GL	I.o.
PROPOSED BY ALLER OF STATE OF THE PROPOSED BY THE PROPOSED BY A PROPOSED	Check	Appropriate Box To Indicate Nature of Notice, Report or	r Other Data
TEMPORABILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting my proposed work) SEE RULE 193. 3875' PB. Pulled rods and pump. Pumped 500 gallons of 15% NB acid down 5-1/2" casing over Jalmat perforations 3396' to 3411' and South Bunice perforations 3778 to 3856'. Flushed with 17 barrels of fresh water. Ran rods and pump and returned well to production. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED ST C. D. BORLAND VILLE Area Production Manager DATE APRIL 7, 1970 APROVED BY ALLE ALLE AREA INC. PARE APRIL 7, 1970	NOTICE OF II	NTENTION TO: SUBSEQU	JENT REPORT OF:
TEMPORABILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting my proposed work) SEE RULE 193. 3875' PB. Pulled rods and pump. Pumped 500 gallons of 15% NB acid down 5-1/2" casing over Jalmat perforations 3396' to 3411' and South Bunice perforations 3778 to 3856'. Flushed with 17 barrels of fresh water. Ran rods and pump and returned well to production. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED ST C. D. BORLAND VILLE Area Production Manager DATE APRIL 7, 1970 APROVED BY ALLE ALLE AREA INC. PARE APRIL 7, 1970			
OTHER OTHER Acidised 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting my proposed work) see role 173. 3875' PB. Pulled rods and pump. Pumped 500 gallons of 15% NE soid down 5-1/2" casing over Jalmat perforations 3396' to 3kill' and South Bunice perforations 3778 to 3856'. Flushed with 17 barrels of fresh water. Ran rods and pump and returned well to production. ONCO 18 1994 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED ST C. D. BORLAND TITLE Dil R See inspector DATE APR 2 1376 APR 2 1376	PERFORM REMED!AL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting may proposed underly state and pump. Pumped 500 gallons of 15% NB acid down 5-1/2" casing over Jalmat perforations 3396' to 3411' and South Emrice perforations 3778 to 3856'. Flushed with 17 barrels of fresh water. Ran rods and pump and returned well to production. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED TO C. D. BORLAND TITLE Area Production Manager DATE APR 3 1370	TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 3875' PB. Pulled rods and pump. Pumped 500 gallons of 15% NB acid down 5-1/2" casing over Jalmat perforations 3396' to 3411' and South Enrice perforations 3778 to 3856'. Flushed with 17 barrels of fresh water. Ran rods and pump and returned well to production. 6767 F. MAA. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED ST. C. D. BORLAND TITLE Area Production Manager DATE APRIL 1376	PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	j . - -
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting cry proposed work; see Rule 1103. 3875' FB. Pulled rods and pump. Pumped 500 gellons of 15% NB acid down 5-1/2" casing over Jelmat perforations 3396' to 3411' and South Banice perforations 3778 to 3656'. Flushed with 17 barrels of fresh water. Ran rods and pump and returned well to production. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. CRIGINAL SIGNED ST. C. D. BORLAND TITLE Area Production Manager OATE April 7, 1970		OTHER	
3875' PB. Pulled rods and pump. Pumped 500 gallons of 15% NB acid down 5-1/2" casing over Jalmat perforations 3396' to 3411' and South Eunice perforations 3778 to 3856'. Flushed with 17 barrels of fresh water. Ran rods and pump and returned well to production. ONCE 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED ST. C. D. BORLAND THE Area Production Manager DATE APROL 1370	OTHER	4-444	
3875' PB. Pulled rods and pump. Pumped 500 gallons of 15% NB acid down 5-1/2" casing over Jalmat perforations 3396' to 3411' and South Eunice perforations 3778 to 3856'. Flushed with 17 barrels of fresh water. Ran rods and pump and returned well to production. ONCE STAND ONCE STAND ONCE STAND THE Area Production Manager DATE APRO 1370 APRO 1370 APRO 1370	17 Describe Proposed or Completed O	perations (Clearly state all pertinent details, and give pertinent dates, inclu-	uding estimated date of starting any proposed
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED ST. TITLE Area Production Manager DATE APRIL 7, 1970 APPROVED BY ALSE LEMENTS TITLE DIE REPROVED BY ALSE LEMENTS DATE	Pulled rods and pur perforations 3396' to	3411' and South Bunies perforations 3778 to	3856'. Flushed with 17
APPROVED BY ALLE DATE DATE	g ^{erin} te filige e o o g		
APPROVED BY ALANDE TITLE DIR DATE	18. I hereby certify that the information ORIGINAL SIGNE	n above is true and complete to the best of my knowledge and belief.	DATE April 7, 1970
	18. I hereby certify that the information ORIGINAL SIGNE	n above is true and complete to the best of my knowledge and belief.	A D A
	ORIGINAL SIGNED C. D. BORLAN	n above is true and complete to the best of my knowledge and belief.	APR 9 1971

RECEIVED

APR 8 1970

OIL CONSERVATION COMM.