

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.
30-025-04886

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Arnott Ramsay(NCT-D)

8. Well No.
5

9. Full name of Wellbore
Eumont Yates, & RVRS, Queen

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator: Chevron USA, Inc.

3. Address of Operator: 15 Smith Rd. Midland, Tx 79705

4. Well Location

Unit Letter G : 1980 feet from the North line and 1980 feet from the East line

Section 33 Township 21-S Range 36-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Notify OCD 24hrs. Prior to MI & RU
2. Set 5 1/2" CIBP @ 3725'(Queen) Spot 20sx plug 3725' to 3525' WOC Tag
3. Displace hole w/MLF, 9.5# Brine w/25 Gel p/BBL
4. Spot 30sx plug 3100' to 2800' (Yates, B-salt)
5. Spot 25sx plug 1700' to 1500' (T-salt) WOC Tag
6. Fill 5 1/2" csg w/35sx plug 320' to surf(8 5/8" shoe - surf) WOC Tag
7. Install dry hole marker

THE COMPLETION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

G.R. Bledsoe

TITLE HES Specialist

DATE 8/15/2002

Type or print name G.R. Bledsoe

(This space for State use)

Telephone No. 687.7153

APPROVED BY

Conditions of approval, if any:

ORIGINAL FILED BY
DATE

APR 22 2002