DISTRIBUTION SANTA FE				Supersedes Old	
SANTA FE	<del>  </del>		Outdeelon	C-102 and C-103	
	NEW MEXICO	OIL CONSERVATION C	OWW1221ON	Effective 1-1-65	
FILE	<del>                                     </del>			5a. Indicate Type of Le	ase
U.S.G.S.	<del>                                     </del>			State 🚺	Fee.
LAND OFFICE	<del>  </del>			5. State Oil & Gas Lea	se No.
OPERATOR				B-229	
CI	JNDRY NOTICES AND REPO	DTS ON WELLS			
OD NOT USE THIS FORM F	OR PROPOSALS TO DRILL OR TO DEEPE PLICATION FOR PERMIT -" (FORM C-1	N OR PLUG BACK TO A DIFFEI 01) FOR SUCH PROPOSALS.)	RENT RESERVOIR.		
•				7. Unit Agreement Nam	e
OIL GAS WELL	OTHER- Doel				
. Name of Operator				8. Farm or Lease Name Arnott-Ramsay	
Gulf Oil Copporation	n			9. Well No.	(402-2)
, Address of Operator	• •			9. Well No.	
Box 670, Hobbs, New	r Mexil.eo			10. Field and Pool, or	Wildcat
Location of Well		Saudh	1980	Jalmat & Sout	
UNIT LETTER		South LINE AND	FEET FROM		
•	99	21-8	36-E		
THE WOST LINE,	SECTION 33 TOWNSHI	RANGE _	имрм.		
mmm	15 Fleygtion (Sh	ow whether DF, RT, GR,	tc.)	12. County	<i>HHHH</i>
			570 GL	Les	
	neck Appropriate Box To In	1: Name of Na	tion Depart on Ot	hor Dota	
EMPORARILY ABANDON	PLUG AND AE Change Plai	COMMENCE DI	RILLING OPNS.	ALTERING C. PLUG AND AE	_
		OTHER			
OTHER			d bala ami	pment & acidis	of So. Bu
·		Unecked	ecen nore edgr	parties of starti	,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	(Classic state all n				ng anv propose
work) SEE RULE 1103.	eted Operations (Clearly state all p	h Rumine same.	Pulled both sta	rings of 2-1/16	1
Work) SEE RULE 1603.  3871 TD.  Pulled hollow roubing. Found all	ds and pump from Sout equipment in good wer id. Ran GOR test on een carried as closed	h Runice sone. king order. Tre South Runice son	Pulled both sta	rings of 2-1/16	n 200
Work) SEE RULE 1703.  Pulled hollow rotubing. Found all gallons of NE FE ac (South Bunice had be original. Signed and the control of the cont	ds and pump from Soutequipment in good werid. Ran GOR test on een carried as closed	h Runice sone. king order. Tre South Runice son in.)	Pulled both stated South Runing and placed bo	rings of 2-1/16	n 000 odustion.
Work) SEE RULE 1703.  Pulled hollow rotubing. Found all gallons of NE FE ac (South Bunice had be original. Signed and the control of the cont	ds and pump from Soutequipment in good werid. Ran GOR test on een carried as closed	to the best of my knowled	Pulled both stated South Runing and placed bo	rings of 2-1/16 lee some with 16 oth somes on pro	n 000 oduotion.
Work) SEE RULE 1703.  3871 TD.  Pulled hollow rotubing. Found all gallons of NE FE ac (South Bunice had be accordingly to the second se	ds and pump from Soutequipment in good werid. Ran GOR test on sem carried as closed	h Bunice sone. king order. Tre South Bunice son in.)	Pulled both stated South Runing and placed bo	rings of 2-1/16 ice some with li	n 000 odustion.