

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1880, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-04905	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. B-1732	
7. Lease Name or Unit Agreement Name W. A. RAMSAY (NCT-A)	
8. Well No. 32	
9. Pool name or Wildcat EUMONT	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3575' GL	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: WENDI KINGSTON	
4. Well Location Unit Letter J : 1980 Feet From The SOUTH Line and 1980 Feet From The EAST Line Section 34 Township 21S Range 36E NMPM LEA County	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTER CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABAN. <input type="checkbox"/> CASING TEST AND CMT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO PLUG AND ABANDON THIS WELL AS FOLLOWS:
PLUG #1, SET CIBP AT 3700' AND SET 5 SX CMT ON TOP.
PLUG #2, PERF & SQZ 40 SX PLUG FROM 1563'-1663', COVERS SALT ZONE.
PLUG #3, PERF & SQZ 40 SX PLUG FROM 372'-472', COVERING 8 5/8" SHOE.
PLUG #4, PERF & SQZ 35 SX PLUG FROM 50'-SURFACE.
ALL PLUGS ARE CLASS C NEAT MIXED AT 14.8 PPG, 1.32 CU/FT SX. DISPLACE HOLE W/9.5 PPG MUD LADEN FLUID. PULL DEAD MAN ANCHORS, FILL PITS, LEVEL LOCATION, PLACE P&A MARKER & CHANGE STATUS OF WELL TO P&A.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE *Wendi Kingston* TITLE TECH. ASSISTANT DATE: 10/27/94
TYPE OR PRINT NAME WENDI KINGSTON TELEPHONE NO. (915)687-7826

APPROVED BY *Wendi Kingston* TITLE TECH. ASSISTANT DATE OCT 31 1994
CONDITIONS OF APPROVAL, IF ANY: