

W MEXICO OIL CONSERVATION COMMISSIO

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent with the the work specified is completed. It should be signed and sworn to before a notary public for report on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

	Indicate 1	nature of repo	t by checking below:		
REPORT ON BEGINNING DRILLING OPERATIONS			REPORT ON REPA	IRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL			REPORT ON PULLING OR OTHERWISE ALTERING CASING		
REPORT ON RESULT OF TEST OF CASING SHUT-OFF 9 5/8"		G XX	REPORT ON DEEPENING WELL		
REPORT ON RE	SULT OF PLUGGING OF W	YELL			
	н	obbs, New M	exico.	February 23,	1940
Santa Fe, New : Gentlemen: Following is a re	eport on the work done and	the results of	Place	ling noted above at th	Date
July 011 Cor	Company or Operator	H. Leonard	Lease	Well No.	in the
ne sw	of Sec.	36	T 21S	, R. 36E	, N. M. P. M.,
Eunice	Field		Lea		County
	s work were as follows:	emented Feb	21, 1940. T	ested Feb 23, 19	40.
testw were 0	drilled and the ho. K and after approva were made to drill Glenn Stach	l of Mr. To ahead. Gulf (orbrough, State	Oil and Gas Insp Field For	reman
Witnessed by	J. D. Henderson	Parker	r Drilling Compa	ny Tool Pusi	Title
	Name		Company	<u></u>	Title
Subscribed and	sworn to before me this		I hereby swear or a is true and correct.	ffirm that the informa	tion given above
23 r 4	day of February	19 40	Name COO	-	9-
J.W. Zarner Notary Public			Position District Superintendent		
				f Oil Corp-Gyps	y Prodn. Div.
My Commission	expires February 25,	1942.	Address Hot	bs. New Mexico.	
Remarks:				Roy 4	arbrough

OIL GAS INSPECTOR