

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-06343

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-11613

7. Lease Name or Unit Agreement Name
NORTHEAST DRINKARD UNIT

8. Well No.
119

9. Pool name or Wildcat
N. EUNICE BLINEBRY-TUBB-DRNKRD

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Shell Western E&P Inc.

3. Address of Operator
P.O. Box 576 Houston, TX 77001-0576

4. Well Location
Unit Letter F : 1650 Feet From The WEST Line and 5610 Feet From The SOUTH Line

Section 2 Township 21S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3507' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ATTEMPTD TO SWG OUT COLLAPSED CSG; SI ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-04 TO 9-16-91:

POH W/RODS. PMP STUCK. RAN FREEPOINT SUR. CHEM CUT TBG @ 2678' & POH. RIH W/SWG. TAG @ 2668'. WORK DWN THRU TI SPOT TO 2682', POH. RIH W/OS. TAG TI SPOT @ 2684' & TOF @ 2687'. ATTEMPTD TO LATCH ONTO FISH, COULD NOT. POH. RIH W/3 IN. IB. TAG TOF @ 2698', POH. SWGD THRU TI SPOT 2684-90', POH. RIH W/4-3/4 IN. SWG. TAG TI SPOT @ 2684'. MADE 1' IN 1 HR, POH. RIH W/4-1/2 IN. SWG. RAN TOOLS THRU TI SPOT TO 2698', POH. RIH W/OS. WORK THRU TI SPOT @ 2684'. LATCH ONTO FISH @ 2698' & POH. REC PROD STRING. SWGD THRU TI SPOT 2684-90' W/4-1/2 IN. SWG, POH. RIH W/4-5/8 IN. SWG. IN 3 HRS, WORK SWG THRU TI SPOT 2685-87', POH. RIH W/4-3/4 SWG. ATTEMPTD TO WORK SWG THRU TI SPOT, COULD NOT. POH. ATTEMPTD TO RIH W/3-3/8 IN. CSG INSP TOOL. COULD NOT GET TOOL BELOW 2651', POH. RIH W/4-3/4 IN. IB. TAG @ 2653', POH. IB INDIC PTD CSG. SI WELL TO EVAL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W. F. N. Kelldorf TITLE DIV. ENVIRONMENTAL ENGR. DATE 10/18/91

TYPE OR PRINT NAME W. F. N. KELLDORF TELEPHONE NO. 713/870-3797

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

OCT 22 1991

RECEIVED

OCT 21 1991

600
HOBBS OFFICE

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-025-06343

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-11613

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

NORTHEAST DRINKARD UNIT

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Shell Western E&P Inc.

8. Well No.

119

3. Address of Operator

P.O. Box 576 Houston, TX 77001-0576

(WICK 4435)

9. Pool name or Wildcat

N. EUNICE BLINEBRY-TUBB-DRNKRD

4. Well Location

Unit Letter F : 1650 Feet From The WEST Line and 5610 Feet From The SOUTH Line

Section 2 Township 21S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3507' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: OAP & ACD ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-10 TO 7-31-90:

POH W/PROD EQUIP. CO TO 6697' (TAGGED FILL). RETAGGED @ 6749'. CO FILL FROM 6749' TO 6843'. PERF'D BLBY/TUBB/DRKD 5777' - 6812' (2 JSPF). ACD PERFS 5777' - 6832' W/11,382 GALS 15% NEFE HCL + 4250# ROCK SALT. INST PROD EQUIP & RETD TO PROD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. H. Smitherman

TITLE

REGULATORY SUPV.

DATE

12/05/90

TYPE OR PRINT NAME

J. H. SMITHERMAN

TELEPHONE NO.

(713) 870-3797

(This space for State Use)

ORIGINAL SIGNATURE

APPROVED BY

DISTRICT

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 11 1990

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06343
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-11613
7. Lease Name or Unit Agreement Name	NORTHEAST DRINKARD UNIT
8. Well No.	119
9. Pool name or Wellcat	NORTH EUNICE BLINEBRY-TUBB- DRINKARD OIL & GAS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	4. Well Location Unit Letter F : 1650 Feet From The WEST Line and 5610 Feet From The SOUTH Line Section 2 Township 21S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3507' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <u>OP & Acdz</u> <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. CO to TOL @ 5955'. CO Inr to @ least 6840'.
3. Perf Bily/Tubb/Drkd 5777' - 6812' (2 JSPF).
4. Acdz perfs 5777' - 6832' w/11,172 gals 15% NEFE HCl + 1450# rock salt.
5. Install prod equip & ret to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. Smitherman TITLE REGULATORY SUPV. DATE 2-23-90
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

FEB 27 1990

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE _____ DATE _____
DISTRICT I SUPERVISOR
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 26 1990

LIBRARY
OF THE
UNITED STATES DEPARTMENT OF JUSTICE