

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-76

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
B-11613	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. CIL ☐ GAS ☐ OTHER- INJECTOR		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
SHELL WESTERN E&P INC.		NORTHEAST DRINKARD UNIT
3. Address of Operator		9. Well No.
P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)		114
4. Location of Well		10. Field and Pool or Widened
UNIT LETTER D 906 FEET FROM THE NORTH LINE AND 660 FEET FROM		NORTH EUNICE BLINEBRY-
THE WEST LINE, SECTION 2 TOWNSHIP 21S RANGE 37E N.M.P.M.		TUBB-DRINKARD OIL & GAS
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3509' DF		LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ cmt sqz, perf & acdz	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. POH w/inj equip.
2. Set pkr @ 5550'.
3. Sqz Blinebry perfs 5736' - 6013' w/50 sx CIs "C" cmt + .3% Halad-9 followed by 50 sx CIs "C" cmt + 2% CaCl₂. WOC 24 hrs.
4. POH w/pkr. CO to top of 3-1/2" lnr @ 5648'.
5. DO cmt to 5830'. Pres tst sqz to 500#. Cont drlg thru cmt & CIBP @ 6240'. CO to TD (6896').
6. Run GR/CCL log from TD to TOL.
7. Perf Blinebry/Tubb/Drinkard 5862' - 6860' (1 JSPF).
8. Acdz perfs 5862' - 6860' w/11,550 gals 15% HCl-NEA + 1750# rock salt using RBP & pkr.
9. POH w/RBP & pkr.
10. Install inj equip, setting Guiberson ER-VI PKR @ ±5600'.

(CONT'D ON REVERSE SIDE)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE 7-13-88

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

11. Pres tst csg to 300# for 30 min.
12. SI well until completion of NE inj leg (est 8-15-88).